


VICTOR REINZ®



MITSUBISHI
Q3 / 2023



VictorReinz.com/online-catalog

Victor Reinz®

at a Glance



Online Catalog

VictorReinz.com/online-catalog



Newsletter

VictorReinz.com/EN/News/Newsletter.aspx?region



Youtube

www.youtube.com/user/VictorReinzSealingEN



Catalog News

VictorReinz.com/news



Technical Service Information

VictorReinz.com/tsi



Facebook

www.facebook.com/VictorReinzParts



Just seal it!

VictorReinz.com/jsi



Technical Datasheet

VictorReinz.com/jsi-datasheet



LinkedIn

www.linkedin.com/showcase/victor-reinz-emea




Safety Datasheet

VictorReinz.com/jsi-datasheet




Homepage


VictorReinz.com



[VictorReinz.com/catalog-info](https://www.victorreinz.com/catalog-info)



[VictorReinz.com/catalog-how-to-use](https://www.victorreinz.com/catalog-how-to-use)



MITSUBISHI



0-9

3A90	5
3A91	6
3A92	6-7
3B20	5
3B20 T	5
4A90	8
4A91	13
4A92	15
4B10	21
4B11	29-31
4B12	38
4B40	13
4D30	54
4D31T	54
4D55	37
4D55 T	37
4D56 (8V)	41
4D56-HP	42
4D56-T	43-48
4D56-TD	43, 48
4D65	21
4D65 T	21
4D68	31
4D68 T	31
4G11	7
4G12	11
4G12 T	12
4G13 (12V)	8-10
4G13 (16V)	11
4G15 (12V)	14
4G15T	14
4G18	16-17
4G32	17-18
4G37	20, 22
4G54	49
4G61	19
4G63 (DOHC 16V)	32
4G63 (SOHC 16V)	32-33
4G63 (SOHC 8V)	34
4G63-T/C	34
4G64 (GDI)	39
4G67	23
4G69	39-40
4G92 (SOHC 16V)	19



4G93 (GDI)	23-24
4G93 (SOHC 16V)	25
4G94	34
4G94 (GDI)	35
4HK	36
4HN	36
4M40-2AT	51
4M40-A	49
4M40-T	50
4M41	54
4N13	25-26
4N14	36, 38
4N15	40
6A12	35
6A13	49
6B31	51
6G72 (DOHC 24V)	52
6G72 (SOHC 24V)	53-54
6G73	49
6G74 (DOHC 24V)	55
6G74 (GDI)	55
6G75	55
9HD	20

B

BKD	27
BSY	28
BWC	27

D

D4BH	41
------	----

F

F8QT	26
F9Q2	27

G

G11B	6
G12B	11
G13B	7
G15B	12
G32B	15
G37B	20
G54B T/C	49
G63B	28-29



G6AT	51
------	----

O

OM 639.939	13
------------	----

















































V

VQ35HR	55
--------	----

MITSUBISHI																	
0,7	3B20	38 kW (52 PS)	i	02/07-12/13	01-37560-01 					61-37560-00 	14-10969-01 1005A425 (8x) 	71-39822-00 1035A486 	12-34223-01 MR984262 (12x) 	11-10401-01 1540A089 (3x) 	70-31414-10 	81-39029-00 1052A266 27x40 AB RD FPM 	81-10404-00 1052A210 85 Ø FPM
0,7	3B20 T	42 kW (57 PS)	i	01/06-12/13	01-37555-01 					61-37555-00 1005A914 	14-10969-01 1005A425 (8x) 	71-39822-00 1035A486 	12-34223-01 MR984262 (12x) 	11-10401-01 1540A089 (3x) 	70-31414-10 	81-39029-00 1052A266 27x40 AB RD FPM 	81-10404-00 1052A210 85 Ø FPM
0,7	3B20 T	47 kW (64 PS)	i	08/10-12/13	01-37555-01 					61-37555-00 1005A914 	14-10276-02 MN158130 (8x) 	71-39822-00 1035A486 	12-34223-01 MR984262 (12x) 	11-10401-01 1540A089 (3x) 	70-31414-10 	81-39029-00 1052A266 27x40 AB RD FPM 	81-10404-00 1052A210 85 Ø FPM
1,0	3A90	52 kW (71 PS)	MIRAGE	05/12						61-34245-00 MN195371 76 Ø 	14-15557-01 1005B939 (8x) 	71-12322-00 1035B076 	12-10031-02 MD179175 (12x) 	71-10030-00 1540A385 	70-31414-10 	81-39028-00 MN195668 29x48 A RD 	81-10389-00 1052B328 LD FPM




MITSUBISHI																
1,1	3A91	55 kW (75 PS)	COLT	10/04-06/12	01-34245-01 					61-34245-00 MN195371 76 Ø 	14-10276-02 MN158130 (8x) 	71-39021-00 MN158378 	12-34223-01 MR984262 (12x) 12x 70-34223-00 MR984262 	71-39022-00 MN149030 3x 71-34912-00 MN163442 	70-31414-10 	81-39028-00 MN195668 29x48 A RD
1,2	G11B	40-53 kW (54-72 PS)			01-52218-03 MD031331 	02-52218-03 MD997012 			61-52218-10 MD030290 72,5 Ø 		71-52219-10 MD030282 		11-52448-01 MD151902 +MD151903 71-52450-00 MD030468 	71-52223-00 MD030133 	81-53232-00 30x46 A SL RD NBR 81-53306-00 MD372250 72x96 A SL LD MVQ 81-53246-00 1052A366 35x50 A SL RD FPM 	
1,2	3A92	55-59 kW (75-80 PS)	MIRAGE	01/12						61-34245-00 MN195371 76 Ø 	14-15557-01 10058339 (6x) 	71-12322-00 10358076 	12-10031-02 MD179175 (12x) 12x 70-10031-00 MD179175 	71-10030-00 1540A385 3x 71-12462-00 1555A647 01/15 → 02/15 71-15554-00 1555A650 03/15 → 		81-39028-00 MN195668 29x48 A RD 81-10389-00 1052B328 LD FPM

MITSUBISHI

<p>Ltr.  3A92</p> <p>58 kW (79 PS)</p> <p>MIRAGE</p> <p> 05/16</p>					<p>61-34245-00 MN195371 76 Ø</p> 	<p>14-15557-01 1005B339 (8x)</p> 	<p>71-12322-00 1035B076</p> 	<p>12-10031-02 MD179175 (12x)</p>  <p>70-10031-00 MD179175</p> 	<p>71-10030-00  3x 1540A385</p>  <p>71-15554-00  1555A650</p> 	<p>70-31414-10</p> 	<p>81-39028-00  MN195668 29x48 A RD</p>  <p>81-10389-00  1052B328 LD FPM</p> 
<p>1,2 4G11</p> <p>40 kW (54-55 PS)</p> <p>LANCER</p> <p>01/80-01/84</p>		<p>02-52218-02 MD997012</p> 			<p>61-52218-10 MD030290 72,5 Ø</p> 		<p>71-52219-10 MD030282</p> 		<p>11-52448-01  MD151902 +MD151903</p>  <p>71-52450-00  MD030468</p> 	<p>71-52223-00 MD030133</p> 	
<p>1,2 4G11</p> <p>40 kW (55 PS)</p> <p>COLT</p> <p>12/78-01/84</p>					<p>61-52218-10 MD030290 72,5 Ø</p> 				<p>11-52448-01  MD151902 +MD151903</p> 	<p>71-52223-00 MD030133</p> 	
<p>1,3 G13B</p> <p>49-51 kW (67-70 PS)</p> <p>COLT LANCER</p> <p>06/86-05/92</p>	<p>01-52475-01 MD997112</p> 	<p>02-52475-01 MD997108</p> 			<p>61-52475-00 MD174496 72,5 Ø</p> 	<p>14-55012-01 MD008769 (10x)</p> 	<p>71-52219-10 MD030282</p> 	<p>12-52718-03 MD115472 (8x)</p> 	<p>11-52448-01  MD151902 +MD151903</p>  <p>71-52450-00  MD030468</p> 	<p>71-52223-00 MD030133</p> 	<p>81-53227-00  MD372248 30x46 A SL RD MVQ</p>  <p>81-53306-00  MD372250 72x96 A SL LD MVQ</p>  <p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p> 


MITSUBISHI																	
1.3	4A90	70 kW (95 PS)	COLT	06/04-06/12	01-34240-01 					61-34240-00 MN195370 76 Ø 	14-10276-01 MN158130 (10x) 	71-39019-00 MN158200 	12-34223-02 MR984262 (16x) 	71-39022-00 4x MN149030 	70-31414-10 	81-39028-00 MN195668 29x48 A RD 	
1.3	4G13 (12V)	49-58 kW (67-78 PS)	LANCER MIRAGE	07/90-08/95						61-52780-00 MD323473 76.5 Ø 	14-55012-01 MD008769 (10x) 		12-52718-01 MD307343 (12x) 	71-52721-00 MD150525 	70-31414-10 	81-53227-00 MD372248 30x46 A SL RD MVQ 	
														81-53306-00 MD372250 72x96 A SL LD MVQ 	81-53246-00 1052A366 35x50 A SL RD FPM 		
1.3	4G13 (12V)	51-55 kW (69-75 PS)	COLT MIRAGE	04/88-05/92	01-52475-02 MD974614 ⇒ 05/90 	02-52475-02 MD974613 ⇒ 05/90 				61-52475-00 MD174496 72.5 Ø ⇒ 05/90 	61-52780-00 MD323473 76.5 Ø ⇒ 06/90 → 	14-55012-01 MD008769 (10x) 	71-52219-10 MD030282 ⇒ 05/90 	12-52718-01 MD307343 (12x) ⇒ 06/90 → 	11-52448-01 MD151902 +MD151903 ⇒ 05/90 	70-31414-10 	81-53227-00 MD372248 30x46 A SL RD MVQ
														81-53306-00 MD372250 72x96 A SL LD MVQ 	81-53246-00 1052A366 35x50 A SL RD FPM 		

mitsubishi


Ltr.  1,3 4G13 (12V) 55 kW (75 PS) COLT  1  04/92-04/96




61-52780-00
MD323473
76.5 Ø




14-55012-01
MD008769 (10x)
⇒ 04/95



12-52718-01
MD307343 (12x)



71-52719-00 
MD311949




71-52721-00 
MD150525



70-31414-10


81-53227-00 
MD372248
30x46
A SL RD MVQ



81-53306-00 
MD372250
72x96
A SL LD MVQ




81-53246-00 **N**
1052A366
35x50
A SL RD FPM




1,3 4G13 (12V) 55 kW (75 PS) LANCER  06/92-12/96


61-52780-00
MD323473
76.5 Ø



14-55012-01
MD008769 (10x)




12-52718-01
MD307343 (12x)



71-52719-00 
MD311949




71-52721-00 
MD150525



70-31414-10


81-53227-00 
MD372248
30x46
A SL RD MVQ




81-53306-00 
MD372250
72x96
A SL LD MVQ















81-53246-00 **N**
1052A366
35x50
A SL RD FPM



mitsubishi
















Ltr.  1,3 4G13 (12V) 55 kW (75 PS) LANCER  09/97-08/03 














































































<p>61-52780-00 MD323473 76.5 Ø</p> 			<p>12-52718-01 MD307343 (12x)</p> 	<p>71-52719-00 </p> <p>MD311949</p>  <p>71-52721-00 </p> <p>MD150525</p> 	<p>70-31414-10</p> 	<p>81-53227-00 </p> <p>MD372248 30x46 A SL RD MVQ</p>  <p>81-53306-00 </p> <p>MD372250 72x96 A SL LD MVQ</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 
---	--	--	--	---	---	--

1,3 4G13 (12V) 58 kW (79 PS) MIRAGE 12/91-08/95
























































































































<p>61-52780-00 MD323473 76.5 Ø</p> 	<p>14-55012-01 MD008769 (10x)  ⇒ 04/95</p>  <p>14-55012-01 MD008769 (10x)</p> 	<p>12-52718-01 MD307343 (12x)</p> 	<p>71-52719-00 </p> <p>MD311949</p>  <p>71-52721-00 </p> <p>MD150525</p> 	<p>70-31414-10</p> 	<p>81-53227-00 </p> <p>MD372248 30x46 A SL RD MVQ</p>  <p>81-53306-00 </p> <p>MD372250 72x96 A SL LD MVQ</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 
---	--	--	---	---	--

mitsubishi












































<p>Ltr.  1,3 4G13 (16V) 60-63 kW (82-86 PS) LANCER SPACE STAR 06/98-12/13  1</p>	<p> 01-53210-01 MD976862</p> 	<p> 02-53210-01 MD976861</p> 	<p></p>	<p></p>	<p> 61-53210-00 MD351292 72 Ø MLS</p> 	<p></p>	<p> 15-53166-01 MD342281 +MD339118 (4X)</p>  <p>71-53904-00 MD342281</p> 	<p> 12-53378-01 MD302172 (8x) +MD307341 (8x)</p> 	<p> 71-53184-00  MD342458</p>  <p>71-53186-00  MR386209</p> 	<p> 70-31414-10</p> 	<p> 81-53232-00  30x46 A SL RD NBR</p>  <p>81-53306-00  MD372250 72x96 A SL LD MVQ</p>  <p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p> 
<p>1,4 G12B 60 kW (82 PS) MIRAGE 03/79-09/83</p>	<p> 01-52222-02 MD997094</p> 	<p> 02-52222-03 MD997013</p> 			<p> 61-52222-00 MD030293 76 Ø</p> 		<p> 71-52219-10 MD030282</p> 	<p> 12-52718-03 MD115472 (8x)</p> 	<p> 11-52448-01  MD151902 +MD151903</p>  <p>71-52450-00  MD030468</p> 	<p> 71-52223-00 MD030133</p> 	<p> 81-53232-00  30x46 A SL RD NBR</p>  <p>81-53306-00  MD372250 72x96 A SL LD MVQ</p>  <p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p> 
<p>1,4 4G12 50-51 kW (68-70 PS) COLT LANCER TREDIA 05/79-08/85</p>	<p> 01-52230-01 MD997113</p> 	<p> 02-52230-01 MD997109</p> 			<p> 61-52230-00 MD016163 76,9 Ø</p> 		<p> 71-52219-10 MD030282</p> 	<p> 12-52718-03 MD115472 (8x)</p> 	<p> 11-52448-01  MD151902 +MD151903</p>  <p>71-52450-00  MD030468</p> 	<p> 71-52223-00 MD030133</p> 	<p> 81-53232-00  30x46 A SL RD NBR</p>  <p>81-53306-00  MD372250 72x96 A SL LD MVQ</p>  <p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p> 

MITSUBISHI

<p>Ltr.  1,4 4G12 T 77 kW (105 PS) COLT LANCER 09/81-01/84  1</p>					<p>61-52230-00 MD016163 76.9 Ø</p> 	<p>14-55012-01 MD008769 (10x)</p> 	<p>71-53193-00 MD346750</p> 	<p>12-52718-03 MD115472 (8x)</p> 		<p>70-31414-10</p> 	<p>81-53227-00 K↔ MD372248 30x46 A SL RD MVQ</p>  <p>81-53306-00 K↔ MD372250 72x96 A SL LD MVQ</p>  <p>81-21798-30 N 35x50 A SL WD ACM</p> 
<p>1,5 G15B 51 kW (70 PS) COLT LANCER 06/85-08/89</p>	<p>01-52230-01 MD997113  12/86</p>  <p>01-52230-03 MD997456  01/87 →</p> 	<p>02-52230-01 MD997109  12/86</p>  <p>02-52230-03 MD997455  01/87 →</p> 		<p>61-52230-00 MD016163 76.9 Ø</p> 		<p>71-52219-10 MD030282</p> 	<p>12-52718-03 MD115472 (8x)</p> 	<p>11-52448-01 </p>  <p>71-52450-00 </p>  <p>71-52452-00 </p> 	<p>71-52223-00 MD030133</p> 	<p>81-53232-00 K↔ 30x46 A SL RD NBR</p>  <p>81-53306-00 K↔ MD372250 72x96 A SL LD MVQ</p>  <p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p> 	
<p>1,5 G15B 60-62 kW (82-84 PS) MIRAGE 05/88-11/91</p>	<p>01-52230-03 MD997456</p> 	<p>02-52230-03 MD997455</p> 		<p>61-52230-00 MD016163 76.9 Ø</p> 		<p>71-52219-10 MD030282</p> 	<p>12-52718-03 MD115472 (8x)</p> 	<p>11-52448-01 </p>  <p>71-52452-00 </p> 	<p>71-52223-00 MD030133</p> 	<p>81-53232-00 K↔ 30x46 A SL RD NBR</p>  <p>81-53306-00 K↔ MD372250 72x96 A SL LD MVQ</p>  <p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p> 	

MITSUBISHI																
Ltr. 																
1,5 OM 639.939	50-70 kW (68-95 PS)	COLT DI-D	08/04-06/12				04-10227-01  	61-37545-00 MN960098 		15-39017-01 MN960102 +MN960103 		71-39018-00  MN960219 	71-39031-00 MN960405 	81-39035-00  MN960033 40x62 A RD PTFE ACM 		
1,5 4A91	77-80 kW (105-109 PS)	COLT LANCER XPANDER MPV	06/04	01-34240-01 				61-34240-00 MN195370 76 Ø 	14-10276-01 MN158130 (10x) 	71-39019-00 MN158200 	12-34223-02 MR984262 (16x) 	71-39022-00  MN149030 	71-34911-00  MN163441 	70-31414-10 	81-39028-00  MN195668 29x48 A RD 	
1,5 4A91	80 kW (109 PS)	COLT	05/06-07/09	01-34240-01 				61-34240-00 MN195370 76 Ø 		71-39019-00 MN158200 	12-34223-02 MR984262 (16x) 	71-39022-00  MN149030 	71-34911-00  MN163441 	70-31414-10 	81-39028-00  MN195668 29x48 A RD 	
1,5 4B40	110-121 kW (150-165 PS)	ECLIPSE	10/17	01-10770-01 1000D173 				61-10770-00 1005C791 76 Ø 0,85 mm MLS 	14-10276-01 MN158130 (10x) 	71-17684-00 1035B339 	12-10031-01 MD179175 (16x) 	71-17696-00  1540A638 	71-17704-00  1515A292 	70-10031-01 MD179175 	70-31414-10 	81-10583-00  1060A243 42x60 A.SL RD FPM 
															81-10389-00  1052B328 LD FPM 	

mitsubishi

Ltr. 											
1,5 4G15 (12V) 61-71 kW (83-97 PS) LANCER MIRAGE 05/88-08/99 					61-52780-00 MD323473 76.5 Ø 		71-52219-10 MD030282 	12-52718-01 MD307343 (12x) 	71-52719-00  MD311949  71-52721-00  MD150525 	71-52223-00 MD030133 	81-53227-00  MD372248 30x46 A SL RD MVQ  81-53306-00  MD372250 72x96 A SL LD MVQ  81-53246-00 N 1052A366 35x50 A SL RD FPM 
1,5 4G15T 110 kW (150 PS) COLT 03/05-06/12	01-53975-01 1000A272 	02-53975-01 1000A271 			61-53975-00 1005A862 		15-53982-01 MD377811 +MD377813 (2x) +MR994294 (2x) 	12-53908-01 MD307341 (8x) +MD302172 (8x)  70-53908-00 ES MD302172 8x  70-53909-00 AS MD307341 8x 	71-53986-00  MN143690  71-53158-00  MR552763 	70-31414-10 	81-53907-00  MD377999 34x46 A SL RD FPM  81-53306-00  MD372250 72x96 A SL LD MVQ  81-53246-00 N 2x 1052A366 35x50 A SL RD FPM 

MITSUBISHI																		
1,6	G32B	48-65 kW (65-88 PS)			<p>01-52235-02 MD997043 1 09/81 → 1 06/84</p>	<p>02-52235-02 MD997014 1 09/81 → 1 06/84</p>			<p>61-52235-10 MD198002 78 0</p>		<p>15-52224-01 MD007383 +MD020718</p>	<p>12-52906-01 MD197467 (8x)</p>	<p>71-52455-00 </p> <p>MD092250 1 07/84 →</p>	<p>71-52454-00 </p> <p>MD302867</p>	<p>71-52229-00 MD008897 1 09/81 → 1 06/84</p>	<p>81-53278-00 </p> <p>44x60 A SL RD NBR</p>	<p>81-53306-00 </p> <p>MD372250 72x96 A SL LD MVQ</p>	<p>81-53246-00 </p> <p>1052A366 35x50 A SL RD FPM</p>
1,6	4A92	85 kW (116 PS)	ASX	05/10	<p>01-34240-02 1000B593</p>				<p>61-34240-00 MN195370 76 0</p>	<p>14-10276-01 MN158130 (10x)</p>	<p>71-10223-00 1035A991</p>	<p>12-10031-01 MD179175 (16x)</p>	<p>11-10030-01 </p> <p>1540A387 +1540A385 (4x)</p>	<p>71-10222-00 </p> <p>1555A555</p>	<p>70-31414-10</p>	<p>81-39028-00 </p> <p>MN195668 29x48 A RD</p>	<p>81-10389-00 </p> <p>1052B328 LD FPM</p>	
1,6	4A92	86 kW (117 PS)	ASX LANCER	05/10	<p>01-34240-02 1000B593</p>				<p>61-34240-00 MN195370 76 0</p>	<p>14-10276-01 MN158130 (10x)</p>	<p>71-10223-00 1035A991</p>	<p>12-10031-01 MD179175 (16x)</p>	<p>11-10030-01 </p> <p>1540A387 +1540A385 (4x)</p>	<p>71-10030-00 </p> <p>1540A385</p>	<p>71-10222-00 </p> <p>1555A555</p>	<p>70-31414-10</p>	<p>81-39028-00 </p> <p>MN195668 29x48 A RD</p>	<p>81-10389-00 </p> <p>1052B328 LD FPM</p>

MITSUBISHI

Ltr. 1,6 4G18 72 kW (98 PS) LANCER 09/03-12/13




01-53880-01
MD979216




02-53880-01
MD978240





61-53880-00
MD342397
MLS




15-53166-01
MD342281
+MD339118 (4x)



71-53904-00
MD342281




12-53908-01
MD307341 (8x)
+MD302172 (8x)



70-53908-00 ES 8x
MD302172



70-53909-00 AS 8x
MD307341




71-53157-00
MR420441



71-53158-00
MR552763



70-31414-10



81-53807-00 K
MD377999
34x46
A SL RD FPM



81-53306-00 K
MD372250
72x96
A SL LD MVQ



81-53246-00 N
1052A366
35x50
A SL RD FPM



1,6 4G18 72 kW (98 PS) SPACE STAR 01/01-12/04

01-53880-01
MD979216




02-53880-01
MD978240



61-53880-00
MD342397
MLS




15-53166-01
MD342281
+MD339118 (4x)



71-53904-00
MD342281



12-53908-01
MD307341 (8x)
+MD302172 (8x)



70-53908-00 ES 8x
MD302172



70-53909-00 AS 8x
MD307341



71-53157-00
MR420441



71-53158-00
MR552763



70-31414-10



81-53227-00 K
MD372248
30x46
A SL RD MVQ
 08/02



81-53907-00 K
MD377999
34x46
A SL RD FPM
 09/02 →






81-53306-00 K
MD372250
72x96
A SL LD MVQ



81-53246-00 N
1052A366
35x50
A SL RD FPM



MITSUBISHI


Ltr.  1,6 4G18  77 kW (105 PS) LANCER  1 06/00-12/07



01-53880-01
MD979216




02-53880-01
MD978240




61-53880-00
MD342281
MLS



15-53166-01
MD342281
+MD339118 (4X)




12-53908-01
MD307341 (8x)
+MD302172 (8x)




70-53908-00 ES 8x
MD302172




70-53909-00 AS 8x
MD307341




71-53157-00 
MR420441





71-53158-00 
MR552763



70-31414-10




81-53227-00 
MD372248
30x46
A SL RD MVQ
 08/02



81-53907-00 
MD377999
34x46
A SL RD FPM
 09/02→




81-53306-00 
MD372250
72x96
A SL LD MVQ





81-53246-00 **N**
1052A366
35x50
A SL RD FPM




1,6 4G32 48-55 kW (65-75 PS) CORDIA GALANT L 300 TREDIA 09/81-04/94


01-52235-02
MD997043
 06/84



02-52235-02
MD997014
 06/84



02-52235-03
MD997136
 07/84→



61-52235-10
MD198002
78 0



15-52224-01
MD007383
+MD020718





12-52906-01
MD197467 (8x)



70-52906-00 8x
MD197467




71-52453-00 
MD034235
 06/84





71-52455-00 
MD192250
 07/84→




71-52454-00 
MD302867



71-52229-00
MD008897
 06/84



81-53278-00 
44x60
A SL RD NBR


















































81-53306-00 
MD372250
72x96
A SL LD MVQ









































81-53246-00 **N**
1052A366
35x50
A SL RD FPM

















































MITSUBISHI

Ltr.	Engine	Power	Model	Region	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11					
1,6	4G32	48-55 kW (65-75 PS)	L 300 SAPPORO	02/80-10/86	01-52235-02 MD997043 1 ⇒ 06/84 	02-52235-02 MD997014 1 ⇒ 09/81 → 1 ⇒ 06/84 				61-52235-10 MD198002 78 Ø 		15-52224-01 MD007383 +MD020718 	12-52906-01 MD197467 (8x) 	71-52453-00  MD034235 1 ⇒ 09/81 → 1 ⇒ 06/84 	71-52455-00  MD192250 1 ⇒ 07/84 → 	71-52454-00  MD302867 	71-52229-00 MD008897 1 ⇒ 09/81 → 1 ⇒ 06/84 	81-53278-00  44x60 A SL RD NBR 	81-53306-00  MD372250 72x96 A SL LD MVQ 	81-53246-00  1052A366 35x50 A SL RD FPM 
1,6	4G32	51 kW (69 PS)	L 400	06/96-10/02		02-52235-03 MD997136 			61-52235-10 MD198002 78 Ø 		15-52224-01 MD007383 +MD020718 	12-52906-01 MD197467 (8x) 	71-52455-00  MD192250 	71-52454-00  MD302867 		81-53278-00  44x60 A SL RD NBR 	81-53306-00  MD372250 72x96 A SL LD MVQ 	81-53246-00  1052A366 35x50 A SL RD FPM 		
1,6	4G32	51 kW (69-70 PS)	L 300	11/84-05/04		02-52235-03 MD997136 			61-52235-10 MD198002 78 Ø 		15-52224-01 MD007383 +MD020718 	12-52906-01 MD197467 (8x) 	71-52455-00  MD192250 	71-52454-00  MD302867 	71-52229-00 MD008897 	81-53278-00  44x60 A SL RD NBR 	81-53306-00  MD372250 72x96 A SL LD MVQ 	81-53246-00  1052A366 35x50 A SL RD FPM 		

MITSUBISHI














































<p>Ltr. </p>	<p>1,6 4G61</p>	<p>91-92 kW (124-125 PS)</p>	<p>COLT MIRAGE</p>	<p>04/88-11/91 </p>		<p>01-52472-01 MD997472</p>			<p>02-52472-01 MD997468</p>					<p>61-52472-00 MD113178 83,5 Ø</p>				<p>15-52469-01</p>			<p>12-52718-02 MD115472 (16x)</p>			<p>71-52912-10  MD188995</p>			<p>71-52476-00 MD040342</p>			<p>81-53279-10  MD343563 44x60 A SL RD FPM</p>		<p>81-53229-10  MD343564 80x96 A SL LD FPM</p>		<p>81-53246-00 N 2x 1052A366 35x50 A SL RD FPM</p>	
<p>1,6 4G92 (SOHC 16V)</p>	<p>66-88 kW (90-120 PS)</p>	<p>CARISMA COLT LANCER MIRAGE</p>	<p>03/92-06/06</p>	<p>01-52785-01 MD970444</p>		<p>02-52785-01 MD970441</p>						<p>61-52785-00 MD184399 82,5 Ø</p>		<p>14-55014-01 MD164738 (10x)</p>		<p>15-52726-01</p>		<p>12-52829-01 MD184303 (16x)</p>		<p>71-52723-00  MD172796</p>		<p>70-31414-10</p>		<p>81-53331-00  MD150161 85x103 A SL LD MVQ</p>		<p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p>									

MITSUBISHI

<p>Ltr. </p>													
<p>1,6 9HD 84 kW (114 PS) ASX Di-D 07/15</p>				<p>04-10340-01 </p> 	<p>61-37940-00 MN982457 75,7 Ø 1,25 mm MLS</p> <p>61-37940-10 MN98245 75,7 Ø 1,3 mm MLS</p> <p>61-37940-20 MN982459 75,7 Ø 1,35 mm MLS</p> <p>61-37940-30 MN982460 75,7 Ø 1,4 mm MLS</p> <p>61-37940-40 MN982461 75,7 Ø 1,45 mm MLS</p> 	<p>14-32336-01 MN982456 (10x)</p> 	<p>71-40903-00 MN982469</p> 	<p>12-35548-01 MN982512 (8x)</p> <p>70-35548-00 MN982512</p> 	<p>71-39037-00 </p> <p>MN982478</p> 	<p>70-31414-10</p> 	<p>81-35554-00 </p> <p>MN982554 40x55 A SL RD PTFE ACM</p>  <p>81-35553-00 </p> <p>MN982447 85x105 A SL LD PTFE ACM</p>  <p>81-35552-00 </p> <p>MN982465 27x47 A SL RD PTFE ACM</p> 		
<p>1,8 G37B 4G37 61-71 kW (83-97 PS) GALANT LANCER SPACE WAGON 10/83-10/92</p>	<p>01-52240-02 MD997514</p> 	<p>02-52240-02 MD997513</p> 			<p>61-52240-00 MD062144 82 Ø</p> 	<p>14-55012-01 MD008769 (10x)</p> 	<p>15-52224-01 MD007383 +MD020718</p> 	<p>12-52906-01 MD197467 (8x)</p> <p>70-52906-00 MD197467</p> 	<p>71-52696-00 </p> <p>MD112095</p>  <p>71-52454-00 </p> <p>MD302867</p> 	<p>71-52229-00 MD008897</p> 	<p>81-53279-10 </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-53306-00 </p> <p>MD372250 72x96 A SL LD MVQ</p>  <p>81-53246-00 </p> <p>1052A366 35x50 A SL RD FPM</p> 		

MITSUBISHI															
1,8	4B10	100-110 kW (136-150 PS)	ASX LANCER	02/08	01-54035-01 1000B334 				61-54035-00 1005B450 87 Ø 0,5 mm 	14-12679-01 1005A755 (8x) +1005A540 (2X) 	71-54092-00 1035A583 	12-54093-01 MD307341 (16x) 70-54093-00 MN183952 	71-54094-00 4x 1542A133 71-54096-00 1555A185 	70-31414-10 	81-54097-00 1052B433 42x55 A SL RD FPM 81-54098-00 1052B333 85x103 A SL LD FPM
1,8	4D65	43-48 kW (58-65 PS)	COLT D GALANT D LANCER D MIRAGE D MIRAGE D	10/83-10/92		02-52255-01 MD997115 		61-52255-00 MD066813 82,5 Ø 	14-55015-02 MD040514 (10x) 	15-52247-01 	12-52906-01 MD197467 (8x) 70-52906-00 MD197467 	71-52458-00 MD070669 	70-31414-10 	81-53279-10 MD343563 44x60 A SL RD FPM 81-53322-10 MD343564 80x96 A SL LD FPM 81-53246-00 1052A366 35x50 A SL RD FPM 	
1,8	4D65 T	55-60 kW (75-82 PS)	GALANT TD SPACE WAGON TD	06/84-10/98	01-52255-03 MD997170 	02-52255-02 MD997134 		61-52255-00 MD066813 82,5 Ø 	14-55015-02 MD040514 (10x) 	15-52247-01 	12-52906-01 MD197467 (8x) 70-52906-00 MD197467 	71-52458-00 MD070669 	70-31414-10 	81-53279-10 MD343563 44x60 A SL RD FPM 81-53322-10 MD343564 80x96 A SL LD FPM 81-53246-00 1052A366 35x50 A SL RD FPM 	



MITSUBISHI

<p>Ltr. </p>	<p>1,8 4G37</p>	<p>66 kW (90 PS)</p>	<p> CORDIA TREDIA</p>	<p> 08/84-07/89</p>		<p>01-52240-01 MD997105</p>			<p>02-52240-01 MD997104</p>							<p>61-52240-00 MD062144 82 Ø</p>			<p>14-55012-01 MD008769 (10x)</p>			<p>15-52224-01 MD007383 +MD020718</p>			<p>12-52906-01 MD197467 (8x)</p>			<p>71-52696-00  MD112095</p>			<p>71-52229-00 MD008897</p>			<p>81-53279-10  MD343563 44x60 A SL RD FPM</p>	
	<p>1,8 4G37</p>	<p>66 kW (90 PS)</p>	<p> LANCER SPACE WAGON</p>	<p>01/84-12/88</p>	<p>01-52240-01 MD997105  ⇒ 01/87</p>		<p>01-52240-02 MD997514  02/87 →</p>		<p>02-52240-01 MD997104  ⇒ 01/87</p>		<p>02-52240-02 MD997513  02/87 →</p>				<p>61-52240-00 MD062144 82 Ø</p>		<p>14-55012-01 MD008769 (10x)</p>		<p>15-52224-01 MD007383 +MD020718</p>		<p>12-52906-01 MD197467 (8x)</p>		<p>71-52696-00  MD112095</p>		<p>71-52454-00  MD302867</p>		<p>71-52229-00 MD008897</p>		<p>81-53279-10  MD343563 44x60 A SL RD FPM</p>						
	<p>03 / 2023</p>																																		

MITSUBISHI															
Ltr.															
1,8	4G67	100 kW (136 PS)	COLT LANCER	11/89-05/92	01-52472-01 MD997472 	02-52472-01 MD997468 			61-52472-00 MD113178 83,5 Ø 	14-55013-01 MD121887 (10x) 	15-52469-01 	12-52718-02 MD115472 (16x) 	71-52912-10 MD188995 71-52471-00 MD124763 	71-52476-00 MD040342 	81-53279-10 MD343563 44x60 A SL RD FPM 81-53322-10 MD343564 80x96 A SL LD FPM 81-53246-00 1052A366 35x50 A SL RD FPM
1,8	4G93 (GDI)	90 kW (122 PS)	CARISMA GDI	10/00-06/06	01-53255-02 MD977793 	02-53255-03 MD977792 			61-53255-00 MD333279 82 Ø MLS 	14-55014-01 MD164738 (10x) 	15-53748-01 MD367805 +MD367806 +10158006 	12-54169-02 MD184303 (16x) 	71-53746-00 MR507780 71-53161-00 MR323599 	70-31414-10 	81-53254-00 MD168055 37x50 A SL RD MVQ 81-10387-00 MD359158 A SL LD FPM 81-53246-00 1052A366 35x50 A SL RD FPM

MITSUBISHI

Ltr. 1.8 4G93 (GDI) 90 kW (122 PS) SPACE STAR GDI 06/98-12/04



61-53255-00
MD333279
82 Ø
MLS



70-54169-00 16x
MD184303



70-31414-10



81-53254-00 K →
MD168055
37x50
A SL RD MVQ



81-53331-00 K →
MD150161
85x103
A SL LD MVQ




81-53246-00 N 2x
1052A366
35x50
A SL RD FPM




1,8 4G93 (GDI) 92 kW (125 PS) CARISMA GDI 09/97-06/06


01-53255-03
MD976072
1 → 06/00




01-53255-02
MD977793
1 → 07/00 →



02-53255-04
MD976071
1 → 02/99



02-53255-01
MD978094
1 → 03/99 →
1 → 06/00




02-53255-03
MD977792
1 → 07/00 →




61-53255-00
MD333279
82 Ø
MLS



14-55014-01
MD184738 (10x)




15-53748-01
MD367805
+MD367806
+10158006
1 → 07/00 →



71-53193-00
MD346750
1 → 03/99 →
1 → 06/00



12-54169-02
MD184303 (16x)



70-54169-00 16x
MD184303



71-53191-00 →
MD360457
1 → 12/97



71-53159-00 →
MD312441
1 → 01/98 →
1 → 06/00



71-53746-00 →
MR507780
1 → 07/00 →



71-53611-00 →
MR497557
1 → 06/00



71-53161-00 →
MR323599
1 → 07/00 →



70-31414-10



81-53254-00 K →
MD168055
37x50
A SL RD MVQ



81-10387-00 K →
MD359158
A SL LD FPM



81-53246-00 N
1052A366
35x50
A SL RD FPM





































MITSUBISHI															
Ltr.															
1,8 4G93 (SOHC 16V)	84 kW (113 PS)	MIRAGE	09/96-08/02		02-53215-01 MD974015 				61-53215-00 MD322820 82 Ø MLS 	14-55014-01 MD164738 (10x) 	71-17506-00 MD307705 	12-54169-02 MD184303 (16x) 	71-53161-00 MR323599 	70-31414-10 	81-53254-00 K MD168055 37x50 A SL RD MVQ
												70-54169-00 MD184303 	16x		81-10387-00 K MD359158 A SL LD FPM
															81-53246-00 N 1052A366 35x50 A SL RD FPM
1,8 4G93 (SOHC 16V)	84-109 kW (114-148 PS)	CARISMA COLT ECLIPSE GALANT LANCER MIRAGE PAJERO SPACE RUNNER SPACE WAGON	10/91-06/07	01-52785-01 MD970444 	02-52785-01 MD970441 			61-52785-00 MD184399 82,5 Ø 	14-55014-01 MD164738 (10x) 	15-52726-01 	12-52829-01 MD184303 (16x) 	71-52723-00 MD172796 	70-31414-10 	81-53331-00 K MD150161 85x103 A SL LD MVQ 	
												71-52724-00 MD157084 		81-53246-00 N 1052A366 35x50 A SL RD FPM 	
1,8 4N13	85 kW (116 PS)	ASX LANCER LANCER DI-D	05/10	01-54168-01 10008255 				61-54100-00 1005B578 84,5 Ø 1,3 mm MLS 	14-13385-01 1005B586 (10x) 	71-54168-00 1035A916 	12-54169-01 MD184303 (8x) +1010A304 (8x) 	71-54172-00 1540A295 	70-31414-10 	81-54174-00 K 1052B061 70x85 A SL RD FPM 	
								61-54100-10 1005B577 84,5 Ø 1,35 mm MLS 			70-54169-00 ES MD184303 	8x	71-54173-00 1555A439 		81-54176-00 K 1052A904 95x111 A SL LD FPM
								61-54100-20 1005B579 84,5 Ø 1,4 mm MLS 			70-54171-00 AS 1010A304 	8x			

















MITSUBISHI														
Ltr.														
1,8 4N13	110 kW (150 PS)	ASX Di-D LANCER Di-D	06/10	<p>01-54168-01 1000B255</p>			<p>04-10301-01 </p> <p> 08/13</p>	<p>61-54100-00 1005B578 84,5 Ø 1,3 mm MLS</p> <p>61-54100-10 1005B577 84,5 Ø 1,35 mm MLS</p> <p>61-54100-20 1005B579 84,5 Ø 1,4 mm MLS</p>	<p>14-13365-01 1005B586 (10x)</p>	<p>71-54168-00 1035A916</p>	<p>12-54169-01 MD184303 (8x) +1010A304 (8x)</p>	<p>71-54172-00 </p> <p>1540A295</p>	<p>70-31414-10</p>	<p>81-54174-00 </p> <p>1052B061 70x85 A SL RD FPM</p> <p>81-54176-00 </p> <p>1052A904 95x111 A SL LD FPM</p>
1,9 F80T	66 kW (90 PS)	CARISMA TD	10/96-09/00		<p>02-26391-07</p>	<p>08-33409-01</p>	<p>61-33685-00 M345348 81 Ø 1,4 mm</p> <p>61-33685-10 M345349 81 Ø 1,5 mm</p> <p>61-33685-20 M345350 81 Ø 1,6 mm</p>	<p>14-32161-01</p>	<p>71-26391-00</p>	<p>12-25837-01</p>	<p>71-33647-00 </p> <p>8x</p>	<p>71-33409-00</p>	<p>81-16737-20 </p> <p>50x68 A SL RD FPM</p> <p>81-23708-50 </p> <p>85x105 A SL LD FPM</p> <p>81-26389-30 </p> <p>M287556 25x42 A SL RD FPM</p>	

mitsubishi






















































Ltr.  2,0 BSY 100-103 kW (136-140 PS) GRANDIS DI-D OUTLANDER DI-D  09/05-11/12

										
	02-36041-01 	08-35038-02 	04-10158-01 	61-33770-00 MN980032 82 Ø 1,55 mm MLS  1  61-33770-10 MN980033 82 Ø 1,63 mm MLS  2  61-33770-20 MN980034 82 Ø 1,71 mm MLS  3 	14-32195-01 MN980035 (10X) 	71-36041-00 	12-31306-01 MN980085 (16X)  70-31306-00 MN980085  16x	71-36121-00  MN980160  71-38428-00  	70-31414-10 	81-34366-00  MN980009 35x48 A SL RD PTFE ACM  81-90018-00  MN980012 PTFE  81-34367-00 N 2x MN980030 32x47 A SL RD PTFE ACM 




























































2,0 G63B 62-64 kW (84-87 PS) L 300 SPACE WAGON 06/86-05/04

				61-52250-00 MD040533 86,5 Ø 		71-52239-00 MD041512 	12-52906-01 MD197467 (8x)  70-52906-00 MD197467  8x	71-52473-00  MD040974  71-52479-00  MD076481 	71-52476-00 MD040342 	81-53278-00  44x60 A SL RD NBR  81-53322-10  MD343564 80x96 A SL LD FPM  81-53246-00 N 1052x366 35x50 A SL LD FPM 
---	---	--	--	--	--	--	---	--	--	---

mitsubishi




























<p>Ltr. </p>	<p></p>	<p></p>											
<p>2,0 G63B 66 kW (90 PS) GALANT 06/86-04/90</p>	<p>01-52250-11 </p>	<p>02-52250-11 </p>			<p>61-52250-00 MD040533 86,5 Ø </p>		<p>71-52239-00 MD041512 </p>		<p>71-52473-00  MD040974 </p>	<p>71-52476-00 MD040342 </p>	<p>81-53278-00  44x60 A SL RD NBR  81-53322-10  MD343564 80x96 A SL LD FPM  81-53246-00 N 1052A366 35x50 A SL RD FPM </p>		
<p>2,0 4B11 105 kW (143 PS) OUTLANDER 10/12</p>					<p>61-54035-00 1005B450 87 Ø 0,5 mm </p>	<p>14-12679-01 1005A755 (6X) +1005A540 (2X) </p>	<p>71-54092-00 1035A583 </p>	<p>12-54093-01 MD307341 (16X)  70-54093-00 MN183952  16x</p>	<p>71-54094-00  1542A133  4x</p>	<p>70-31414-10 </p>	<p>81-54097-00  1052B433 42x55 A SL RD FPM  81-54098-00  1052B333 85x103 A SL LD FPM </p>		
<p>2,0 4B11 108-118 kW (147-160 PS) LANCER 03/07</p>	<p>01-54035-01 1000B334 </p>				<p>61-54035-00 1005B450 87 Ø 0,5 mm </p>	<p>14-12679-01 1005A755 (6X) +1005A540 (2X) </p>	<p>71-54092-00 1035A583 </p>	<p>12-54093-01 MD307341 (16X)  70-54093-00 MN183952  16x</p>	<p>71-54094-00  1542A133  4x 71-54096-00  1555A185 </p>	<p>70-31414-10 </p>	<p>81-54097-00  1052B433 42x55 A SL RD FPM  81-54098-00  1052B333 85x103 A SL LD FPM </p>		

MITSUBISHI









<p>Ltr. </p>											
<p>2,0 4B11 118 kW (160 PS) ASX 06/10</p>	<p>01-54035-02 1000B452</p> 				<p>61-54035-00 1005B450 87 Ø 0,5 mm</p> 	<p>14-12679-01 1005A755 (8X) +1005A540 (2X)</p>  <p>14-12679-02 1005A755 (10X)</p> 	<p>71-54092-00 1035A583</p> 	<p>12-54093-01 MD307341 (16X)</p>  <p>70-53909-00 MD307341</p>  <p>70-54093-00 MN183952</p> 	<p>71-54094-00  4x 1542A133</p>  <p>71-12676-00  1555A560</p> 	<p>70-31414-10</p> 	<p>81-54097-00  1052B433 42x55 A SL RD FPM</p>  <p>81-54098-00  1052B333 85x103 A SL LD FPM</p> 
<p>2,0 4B11 118 kW (160 PS) OUTLANDER 03/13</p>					<p>61-54035-00 1005B450 87 Ø 0,5 mm</p> 	<p>14-12679-02 1005A755 (10X)</p> 		<p>12-54093-01 MD307341 (16X)</p>  <p>70-53909-00 MD307341</p> 	<p>71-54094-00  4x 1542A133</p> 	<p>70-31414-10</p> 	<p>81-54097-00  1052B433 42x55 A SL RD FPM</p>  <p>81-54098-00  1052B333 85x103 A SL LD FPM</p> 
<p>2,0 4D68 4D68 T 50-66 kW (68-90 PS) GALANT GALANT TDI LANCER D MIRAGE 12/91-10/04</p>	<p>01-52247-01 MD971654</p> 	<p>02-52247-01 MD971653</p> 			<p>61-52965-10 MD301578 84 Ø 1,4 mm</p>  <p>61-52965-20 MD301579 84 Ø 1,45 mm</p>  <p>61-52965-30 MD301580 84 Ø 1,5 mm</p> 	<p>14-55048-01 MD191474 (10x)</p> 	<p>15-52247-01</p> 	<p>12-52906-01 MD197467 (8x)</p>  <p>70-52906-00 MD197467</p> 	<p>71-52918-00  4x</p>  <p>71-52459-00  MD084230</p> 	<p>70-31414-10</p> 	<p>81-53278-00  44x60 A SL RD NBR</p>  <p>81-53331-00  MD150161 85x103 A SL LD MVQ</p>  <p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p> 

mitsubishi




Ltr.  2,0 4G63 (DOHC 16V) 99-100 kW (135-136 PS) LANCER OUTLANDER  05/03-12/13  1

										
<p>01-10000-01 MD979312</p> 	<p>02-10000-01 MD979311</p> 			<p>61-10015-00 MD332034 86,5 Ø MLS</p> 	<p>14-55075-01 MD191470 (10x)</p> 	<p>15-10005-01 MD340535 +MD186785 (4x)</p> 	<p>12-53396-02 MD306079 (8x) +MD307343 (8x)</p> 	<p>71-10146-00  1540A019</p>  <p>71-52908-00  MD181032</p> 	<p>70-31414-10</p> 	<p>81-53279-10  MD343563 44x60 A SL RD FPM</p>  <p>81-10387-00  MD359158 A SL LD FPM</p>  <p>81-53246-00 N 2x 1052A366 35x50 A SL RD FPM</p> 

2,0 4G63 (SOHC 16V) 80 kW (109 PS) SPACE WAGON 12/98-06/02


				<p>61-10015-00 MD332034 86,5 Ø MLS</p> 			<p>70-54169-00 16x MD184303</p> 		<p>70-31414-10</p> 	<p>81-53279-10  MD343563 44x60 A SL RD FPM</p>  <p>81-53331-00  MD150161 85x103 A SL LD MVQ</p>  <p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p> 
--	--	--	--	---	--	--	--	--	---	--


mitsubishi

Ltr.  2,0 4G63 (SOHC 16V) 98 kW (133 PS) SPACE WAGON GDI  10/98-12/04 



2,0 4G63 (SOHC 16V) 98-100 kW (133-136 PS) GALANT 09/96-10/04

61-10015-00
MD332034
86,5 Ø
MLS


70-54169-00 16x
MD184303



71-52908-00 
MD181032




70-31414-10


81-53279-10 K↔
MD343563
44x60
A SL RD FPM

81-53331-00 K↔
MD150161
85x103
A SL LD MVQ

81-53246-00 N
1052A366
35x50
A SL RD FPM


61-10015-00
MD332034
86,5 Ø
MLS


12-54169-02
MD184303 (16x)

70-54169-00 16x
MD184303


71-52908-00 
MD181032















































































70-31414-10


81-53279-10 K↔
MD343563
44x60
A SL RD FPM




81-10387-00 K↔
MD359158
A SL LD FPM

81-53246-00 N
1052A366
35x50
A SL RD FPM


MITSUBISHI


<p>Ltr. </p>	<p>2,0 4G63 (SOHC 8V) 65-82 kW (88-112 PS)</p>	<p>GALANT L 300 SAPPORO</p>	<p>08/80-02/87 </p>		<p>01-52950-01 MD971623</p> 		<p>02-52950-01</p> 						<p>61-52950-00 MD199174 86 Ø</p> 				<p>15-52911-01</p> 		<p>12-52829-01 MD184303 (16x)</p> 		<p>71-52907-00 </p>  <p>71-52908-00 </p>  <p>71-52909-00  </p> 		<p>71-52899-00</p> 		<p>81-53279-10 </p>  <p>MD343563 44x60 A SL RD FPM</p> <p>81-53331-00 </p>  <p>MD150161 85x103 A SL LD MVQ</p> <p>81-53246-00 </p>  <p>1052A366 35x50 A SL RD FPM</p> 
<p>2,0 4G63-T/C</p>	<p>132 kW (180 PS)</p>	<p>STARION</p>	<p>05/85-08/87</p>		<p>01-52250-11</p> 		<p>02-52250-11</p> 						<p>61-52250-00 MD040533 86,5 Ø</p> 				<p>71-52239-00 MD041512</p> 		<p>12-52906-01 MD197467 (8x)</p> 		<p>71-52473-00 </p>  <p>71-52479-00 </p> 		<p>71-52476-00 MD040342</p> 		<p>81-53278-00 </p>  <p>44x60 A SL RD NBR</p> <p>81-53322-10 </p>  <p>MD343564 80x96 A SL LD FPM</p> <p>81-53246-00 </p>  <p>1052A366 35x50 A SL RD FPM</p> 
<p>2,0 4G94</p>	<p>96-103 kW (131-140 PS)</p>	<p>PAJERO</p>	<p>10/02-02/15</p>										<p>61-10759-00 MD367277 82 Ø 0,42 mm MLS</p> 				<p>71-17506-00 MD307705</p> 		<p>12-52829-01 MD184303 (16x)</p> 		<p>71-17504-00 </p>  <p>71-53161-00 </p> 		<p>70-31414-10</p> 		<p>81-53254-00 </p>  <p>MD168055 37x50 A SL RD MVQ</p> <p>81-53331-00 </p>  <p>MD150161 85x103 A SL LD MVQ</p> 

mitsubishi


Ltr.  2,0 4G94 (GDI) 95 kW (129 PS)  PAJERO GDI  1 10/00-06/07



01-10759-01
MD978115




02-10759-02
MD978114




61-10759-00
MD367277
82 Ø
0,42 mm
MLS





14-55014-01
MD164738 (10x)





15-53748-01
MD367805
+MD367806
+10158006




12-54169-02
MD184303 (16x)



71-53191-00 
MD360457



71-53161-00 
MR323599



70-31414-10



81-53254-00 
MD168055
37x50
A SL RD MVQ



81-10387-00 
MD359158
A SL LD FPM



81-53246-00 **N** 2x
1052A366
35x50
A SL RD FPM




2,0 6A12 110 kW (150 PS) GALANT V6 11/92-08/96


01-52790-01




02-52790-01




61-52790-00 2x
MD198014
80 Ø




14-55014-01
MD164738 (10x)





71-52897-00 2x
MD174560



12-52829-03
MD184303 (24x)



71-52901-00  2x




71-52902-00  2x

70-31414-10



81-53254-00 
MD168055
37x50
A SL RD MVQ



81-53331-00 
MD150161
85x103
A SL LD MVQ






81-53246-00 **N**
1052A366
35x50
A SL RD FPM






MITSUBISHI

Ltr.  2.2 4HK 4HN 115 kW (156 PS) OUTLANDER DI-D  08/07-11/12



2.2 4HK 4HN 115 kW (156 PS) OUTLANDER DI-D 08/07-11/12




61-35805-00
MN982019
85,9 Ø
1,25 mm
MLS


61-35805-10
MN982020
85,9 Ø
1,3 mm
MLS

61-35805-20
MN982021
85,9 Ø
1,35 mm
MLS


61-35805-30
MN982022
85,9 Ø
1,4 mm
MLS




14-35774-01
MN982023 (10x)




15-38554-01
MN982027
+MN982033 (2x)
+MN982032




71-38552-00
MN982033 2x




71-38554-00
MN982032





12-38539-01
MN982147 (16x)





70-38539-00
MN982147 16x




11-38553-01 



71-35919-00 
MN982252



70-31414-10



81-36557-00 
MN982075
42x62
A SL RD PTFE



81-36556-00 
MN982076
90x110
A SL LD PTFE




81-34144-00 **N**
MN982134
27x47
A SL RD FPM




2.2 4N14 103-132 kW (140-179 PS) ASX DI-D OUTLANDER DI-D 11/06



01-10301-01
1000B907





01-10301-02
1000B906



01-10301-03
1000B908


04-10301-01 



61-10301-00
1005C142
87,5 Ø
1,3 mm
MLS

61-10301-10
1005C141
87,5 Ø
1,35 mm
MLS

61-10301-20
1005C143
87,5 Ø
1,4 mm
MLS



14-13365-01
1005B586 (10x)



71-54168-00
1035A916



12-54169-01
MD184303 (8x)
+1010A304 (8x)





70-54169-00 **ES** 8x
MD184303





70-54171-00 **AS** 8x
1010A304



71-54172-00 
1540A295





71-54173-00 
1555A439





70-31414-10

















































81-54174-00 
1052B061
70x85
A SL RD FPM



81-54176-00 
1052A904
95x111
A SL LD FPM
































MITSUBISHI

<p>Ltr.  4D55</p> <p> L 300 D</p> <p> 04/83-10/86</p>											
<p>2,3 4D55 50 kW (68 PS)</p>	<p>01-52248-01 MD050092</p> 	<p>02-52248-01 MD050092</p> 			<p>61-52248-10 MD050545 92,5 Ø</p> 	<p>14-55015-01 MD040514 (18x)</p> 	<p>15-52244-02 MD050312 +MD050536 +MD000523 (3x)</p> 	<p>12-52906-01 MD197467 (8x)</p>  <p>70-52906-00 MD197467</p>  <p>8x</p>	<p>71-52463-00  </p> <p>MD050482</p> 	<p>71-52462-00 MD149392</p> 	<p>81-53279-10 K </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-53322-10 K </p> <p>MD343564 80x96 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 
<p>2,3 4D55 T 62 kW (84 PS)</p> <p>GALANT TD PAJERO TD</p> <p>09/80-04/86</p>	<p>01-53990-01 MD974500</p> 	<p>02-53990-01 MD974499</p> 			<p>61-53990-00 MD149577</p> 	<p>14-55015-01 MD040514 (18x)</p> 	<p>15-52244-02 MD050312 +MD050536 +MD000523 (3x)</p> 	<p>12-52906-01 MD197467 (8x)</p>  <p>70-52906-00 MD197467</p>  <p>8x</p>	<p>71-53732-00  </p> <p>MR188679</p> 	<p>71-52462-00 MD149392</p> 	<p>81-53279-10 K </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-53322-10 K </p> <p>MD343564 80x96 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 




















MITSUBISHI															
2,3	4N14	110-130 kW (150-177 PS)	OUTLANDER DI-D	09/10	<p>01-10301-01 1000B907</p> <p>01-10301-02 1000B906</p> <p>01-10301-03 1000B908</p>			<p>04-10301-01 </p>	<p>61-10301-00 1005C142 87,5 Ø 1,3 mm MLS</p> <p>61-10301-10 1005C141 87,5 Ø 1,35 mm MLS</p> <p>61-10301-20 1005C143 87,5 Ø 1,4 mm MLS</p>	<p>14-13365-01 1005B586 (10x)</p>	<p>71-54168-00 1035A916</p>	<p>12-54169-01 MD184303 (8x) +1010A304 (8x)</p> <p>70-54169-00 ES 8x MD184303</p> <p>70-54171-00 AS 8x 1010A304</p>	<p>71-54172-00 </p> <p>1540A295</p> <p>71-54173-00 </p> <p>1555A439</p>	<p>70-31414-10</p>	<p>81-54174-00 </p> <p>1052B061 70x85 A SL RD FPM</p> <p>81-54176-00 </p> <p>1052A904 95x111 A SL LD FPM</p>
2,4	4B12	123-125 kW (167-170 PS)	ASX LANCER OUTLANDER	11/06	<p>01-10239-01 1000A523</p>			<p>61-10239-00 1005B451 89 Ø 0,5 mm MLS</p>	<p>14-12679-01 1005A755 (8x) +1005A540 (2x)</p>	<p>71-54092-00 1035A583</p>	<p>12-54093-01 MD307341 (16x)</p> <p>70-54093-00 16x MN183952</p>	<p>71-54094-00 </p> <p>1542A133</p> <p>71-54096-00 </p> <p>1555A185</p>	<p>70-31414-10</p>	<p>81-54097-00 </p> <p>1052B433 42x55 A SL RD FPM</p> <p>81-54098-00 </p> <p>1052B333 85x103 A SL LD FPM</p>	
2,4	4B12	153 kW (208 PS)	OUTLANDER	09/18				<p>61-10239-00 1005B451 89 Ø 0,5 mm MLS</p>		<p>71-54092-00 1035A583</p>	<p>70-54093-00 16x MN183952</p>	<p>71-54094-00 </p> <p>1542A133</p> <p>71-12676-00 </p> <p>1555A560</p>	<p>70-31414-10</p>	<p>81-54097-00 </p> <p>1052B433 42x55 A SL RD FPM</p> <p>81-54098-00 </p> <p>1052B333 85x103 A SL LD FPM</p>	

mitsubishi

Ltr.  2,4 4G64 (GDI) 98-110 kW (133-150 PS) GALANT GDI GRANDIS GDI LANCER GDI OUTLANDER PA SPACE RUNNER GDI SPACE WAGON GDI  1 11/97-12/13




										
				<p>61-10768-00 MD361466 88 Ø 0,4 mm MLS</p> 	<p>14-55075-01 MD191470 (10X)</p> 	<p>71-17664-00 MD348283</p> 	<p>12-53396-02 MD306079 (8x) +MD307343 (8x)</p> 	<p>71-17519-00  2x MR560456</p>  <p>71-17507-00  MR552451</p> 	<p>70-31414-10</p> 	<p>81-53279-10  K </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-10387-00  K </p> <p>MD359158 A SL LD FPM</p>  <p>81-53246-00 N 2x</p> <p>1052A366 35x50 A SL RD FPM</p> 

2,4 4G69 116-121 kW (158-165 PS) GALANT GALANT GDI 10/03

				<p>61-10040-00 MN163381 88 Ø MLS</p> 		<p>71-10235-00 MN137117</p> 	<p>12-54169-02 MD184303 (16x)</p>  <p>70-54169-00 16x MD184303</p> 	<p>71-10233-00  K </p> <p>MN171073</p>  <p>71-10234-00  1555A052</p> 	<p>70-31414-10</p> 	<p>81-53279-10  K </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-10387-00  K </p> <p>MD359158 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 
---	---	--	--	---	--	--	--	--	---	--

MITSUBISHI																	
Ltr.	2,4 4G69	118-130 kW (160-177 PS)	ECLIPSE GRANDIS OUTLANDER		03/01-12/12	<p>01-10003-01 MD979394</p>	<p>02-10003-01 MD979393</p>				<p>61-10040-00 MN163381 88 Ø MLS</p>	<p>14-55075-01 MD191470 (10x)</p>	<p>71-10235-00 MN137117</p>	<p>12-54169-02 MD184303 (16x)</p> <p>70-54169-00 MD184303</p> <p>16x</p>	<p>71-10233-00 </p> <p>MN171073</p> <p>71-10234-00 </p> <p>1555A052</p>	<p>70-31414-10</p>	<p>81-53279-10 </p> <p>MD343563 44x60 A SL RD FPM</p> <p>81-10387-00 </p> <p>MD359158 A SL LD FPM</p> <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p>
Ltr.	2,4 4N15	112-140 kW (152-190 PS)	L 200 D L 200 DI-D PAJERO DI-D		11/14	<p>01-10304-01 1000D061</p> <p>01-10304-02 1000D062</p> <p>01-10304-03 1000D063</p>				<p>61-10304-00 1005C723 87,5 Ø 1,3 mm MLS</p> <p>61-10304-10 1005C722 87,5 Ø 1,35 mm MLS</p> <p>61-10304-20 1005C724 87,5 Ø 1,4 mm MLS</p>	<p>14-13365-01 1005B586 (10x)</p>	<p>71-13298-00 1035B281</p>	<p>12-54169-01 MD184303 (8x) +1010A304 (8x)</p> <p>70-54169-00 ES</p> <p>MD184303</p> <p>70-54171-00 AS</p> <p>1010A304</p> <p>8x</p> <p>8x</p>	<p>71-54172-00 </p> <p>1540A295</p> <p>71-13299-00 </p> <p>1555A772</p>	<p>70-31414-10</p>	<p>81-10507-00 </p> <p>1052B382 70x85 A SL RD FPM</p> <p>81-54176-00 </p> <p>1052A904 95x111 A SL LD FPM</p>	

MITSUBISHI

Ltr.  2,5 D4BH 73 kW (99 PS) GALLOPER TD INTERCOOLER  09/98-12/03 





01-52252-03
1000A901





02-52252-03
1000A915




61-52252-10
1005B425
92,5 Ø
1,45 mm  2


61-52252-20
1005B426
92,5 Ø
1,5 mm  3

61-52252-30
1005B427
92,5 Ø
1,55 mm  4

61-52252-40
1005B428
92,5 Ø
1,6 mm  5





14-55015-01
MD040514 (18x)




15-52244-02
MD050312
+MD050536
+MD000523 (3x)




12-52906-01
MD197467 (8x)



71-52463-00  
MD050482



71-52462-00
MD149392



81-53279-10  
MD343563
44x60
A SL RD FPM



81-53322-10  
MD343564
80x96
A SL LD FPM




81-53246-00 **N**
1052A366
35x50
A SL RD FPM



2,5 4D56 (8V) 51-55 kW (69-75 PS) L 200 D L 300 L 300 D 11/86-12/07


01-52248-01
MD050092




02-52248-01
MD050092



61-52248-10
MD050545
92,5 Ø




14-55015-01
MD040514 (18x)



15-52244-02
MD050312
+MD050536
+MD000523 (3x)



12-52906-01
MD197467 (8x)





71-52463-00  
MD050482



71-52462-00
MD149392



81-53279-10  
MD343563
44x60
A SL RD FPM








































81-53322-10  
MD343564
80x96
A SL LD FPM





























































81-53246-00 **N**
1052A366
35x50
A SL RD FPM






MITSUBISHI

<p>Ltr. </p>	<p>2,5 4D56-HP 94-131 kW (128-178 PS) L 200 DiD L 200 DI-D PAJERO DI-D</p>	<p>11/05</p>											
<p>2,5 4D56-HP 123-131 kW (167-178 PS) L 200 DI-D PAJERO DI-D</p>	<p>08/07</p>	<p>01-16987-01 1005B819 92,75 Ø 1,07 mm MLS</p> 	<p>02-16987-01</p> 	<p>04-10206-01 </p> 	<p>61-10645-00 1005B819 92,75 Ø 1,07 mm MLS</p> <p>61-10645-10 1005B897 92,75 Ø 1,12 mm MLS</p> <p>61-10645-20 1005D179 92,75 Ø 1,17 mm MLS</p> 	<p>14-17028-01 1005A327 (18x)</p> 	<p>15-16987-01 1035A108 +MN158385 (4x) +MN149704 (3x) +MN149705 (1x) +1052A099 (4x)</p> 	<p>12-54169-02 MD184303 (16x)</p> <p>70-54169-00 MD184303</p> 	<p>11-16988-01 </p> <p>1540A049 +1540A050</p>  <p>71-16992-00 </p> <p>1555A051</p> 	<p>70-31414-10 </p>  <p>71-17027-00 1200A147</p> 	<p>81-53279-10 </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-10544-00 </p> <p>MN128731 91x107 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 	<p>81-53279-10 </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-10544-00 </p> <p>MN128731 91x107 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 	

MITSUBISHI

<p>Ltr. </p>													
<p>2,5 4D56-T 4D56-TD</p> <p>62-73 kW (84-99 PS)</p> <p>L 200 TD L 300 D L 300 TD L 400 TD PAJERO TD SPACE GEAR TD</p>	<p>01-52252-03 1000A901</p> 	<p>02-52252-03 1000A915</p> 			<p>61-52252-10 1005B425 92,5 Ø 1,45 mm</p> <p>61-52252-20 1005B426 92,5 Ø 1,5 mm</p> <p>61-52252-30 1005B427 92,5 Ø 1,55 mm</p> <p>61-52252-40 1005B428 92,5 Ø 1,6 mm</p> 	<p>14-55015-01 MD040514 (18x)</p> 	<p>15-52244-02 MD050312 +MD050536 +MD000523 (3x)</p> 	<p>12-52906-01 MD197467 (8x)</p> <p>70-52906-00 MD197467</p> 	<p>71-53732-00  </p> <p>MR188679</p> 	<p>70-31414-10</p> 	<p>81-53279-10 K </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-53322-10 K </p> <p>MD343564 80x96 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 		
<p>2,5 4D56-T</p> <p>64 kW (87 PS)</p> <p>L 300 TD</p>	<p>01-52252-03 1000A901  ⇒ 08/01</p>  <p>01-52244-01 MD978645  ⇒ 09/01→</p> 	<p>02-52252-03 1000A915  ⇒ 08/01</p>  <p>02-52244-01 MD972999  ⇒ 09/01→</p> 			<p>61-52252-10 1005B425 92,5 Ø 1,45 mm  ⇒ 08/01</p> <p>61-52252-20 1005B426 92,5 Ø 1,5 mm  ⇒ 08/01</p> <p>61-52252-30 1005B427 92,5 Ø 1,55 mm  ⇒ 08/01</p> <p>61-52252-40 1005B428 92,5 Ø 1,6 mm  ⇒ 08/01</p>  <p>61-53700-00 MD377774 92 Ø 1,45 mm MLS  ⇒ 09/01→</p> <p>61-53700-10 MD377775 92 Ø 1,5 mm MLS  ⇒ 09/01→</p> <p>61-53700-20 MD377776 92 Ø 1,55 mm MLS  ⇒ 09/01→</p> 	<p>14-55015-01 MD040514 (18x)</p> 	<p>15-52244-02 MD050312 +MD050536 +MD000523 (3x)</p> 	<p>12-52906-01 MD197467 (8x)</p> <p>70-52906-00 MD197467</p> 	<p>71-53732-00  </p> <p>MR188679</p> 	<p>70-31414-10</p> 	<p>81-53279-10 K </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-53322-10 K </p> <p>MD343564 80x96 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 		

mitsubishi

Ltr.  2,5 4D56-T 66-98 kW (90-133 PS)  L 200 TD  1 08/01-12/07



01-52252-03
1000A901
1 ⇒ 08/01





01-52244-01
MD978645
1 ⇒ 09/01 →



02-52252-03
1000A915
1 ⇒ 08/01



02-52244-01
MD972999
1 ⇒ 09/01 →



04-10001-01 



61-52252-10
1005B425
92,5 Ø
1,45 mm
1 ⇒ 08/01

61-52252-20
1005B426
92,5 Ø
1,5 mm
1 ⇒ 08/01

61-52252-30
1005B427
92,5 Ø
1,55 mm
1 ⇒ 08/01

61-52252-40
1005B428
92,5 Ø
1,6 mm
1 ⇒ 08/01



61-53700-00
MD37774
92 Ø
1,45 mm
MLS
1 ⇒ 09/01 →

61-53700-10
MD37775
92 Ø
1,5 mm
MLS
1 ⇒ 09/01 →


61-53700-20
MD37776
92 Ø
1,55 mm
MLS
1 ⇒ 09/01 →




14-55015-01
MD040514 (18x)




15-52244-02
MD050312
+MD050536
+MD000523 (3x)



12-52906-01
MD197467 (8x)




70-52906-00
MD197467 8x



71-53732-00  



70-31414-10



81-53279-10 

MD343563
44x60
A SL RD FPM



81-53322-10 

MD343564
80x96
A SL LD FPM





81-53246-00 

1052A366
35x50
A SL RD FPM



MITSUBISHI

Ltr.  2,5 4D56-T 73 kW (99 PS)  PAJERO TD  1 11/98



04-10236-01 


61-52252-20
1005B426
92,5 Ø
1,5 mm 


61-52252-30
1005B427
92,5 Ø
1,55 mm 

61-52252-40
1005B428
92,5 Ø
1,6 mm 




61-53700-00
MD37774
92 Ø
1,45 mm
MLS

61-53700-10
MD37775
92 Ø
1,5 mm
MLS 

61-53700-20
MD37776
92 Ø
1,55 mm
MLS 




14-55015-01
MD040514 (18x)






15-52244-02
MD050312
+MD050536
+MD000523 (3x)



12-52906-01
MD197467 (8x)



71-53732-00   
MR188679




70-31414-10 




81-53279-10 
MD343563
44x60
A SL RD FPM




81-53322-10 
MD343564
80x96
A SL LD FPM









81-53246-00 
1052A366
35x50
A SL RD FPM





mitsubishi


Ltr.  2,5 4D56-T 73 kW (99 PS)  PAJERO TDI  1 04/00-12/06





61-52252-20
1005B426
92,5 Ø
1,5 mm
 ⇒ 06/01

61-52252-30
1005B427
92,5 Ø
1,55 mm
 ⇒ 06/01

61-52252-40
1005B428
92,5 Ø
1,6 mm
 ⇒ 06/01



61-53700-00
MD377774
92 Ø
1,45 mm
MLS
 ⇒ 07/01→

61-53700-10
MD377775
92 Ø
1,5 mm
MLS
 ⇒ 07/01→

61-53700-20
MD377776
92 Ø
1,55 mm
MLS
 ⇒ 07/01→




14-55015-01
MD040514 (18x)

15-52244-02
MD050312
+MD050536
+MD000523 (3x)



12-52906-01
MD197467 (8x)



70-52906-00
MD197467



8x



70-31414-10



81-53279-10 K↔
MD343563
44x60
A SL RD FPM



81-53322-10 K↔
MD343564
80x96
A SL LD FPM



81-53246-00 N
1052A366
35x50
A SL RD FPM



2,5 4D56-T 73 kW (99 PS) PAJERO TDIC 03/91-08/99

61-52252-10
1005B425
92,5 Ø
1,45 mm

61-52252-20
1005B426
92,5 Ø
1,5 mm

61-52252-30
1005B427
92,5 Ø
1,55 mm

61-52252-40
1005B428
92,5 Ø
1,6 mm




14-55015-01
MD040514 (18x)

15-52244-02
MD050312
+MD050536
+MD000523 (3x)



12-52906-01
MD197467 (8x)






70-52906-00
MD197467



8x



71-53732-00   



70-31414-10



81-53279-10 K↔
MD343563
44x60
A SL RD FPM











































81-53322-10 K↔
MD343564
80x96
A SL LD FPM






81-53246-00 N
1052A366
35x50
A SL RD FPM



























mitsubishi























<p>Ltr. </p>	<p>2,5 4D56-T</p>	<p>85 kW (115 PS)</p>	<p>L 200 TD</p>	<p>09/01-12/07 </p>											
<p>2,5 4D56-T</p>	<p>85 kW (115 PS)</p>	<p>PAJERO TDI PAJERO TDI</p>	<p>09/01-12/06</p>	<p>01-52244-01 MD978645</p> 	<p>02-52244-01 MD972999</p> 		<p>04-10001-01 </p> 	<p>61-53700-00 MD37774 92 Ø 1,45 mm MLS</p> <p>61-53700-10 MD37775 92 Ø 1,5 mm MLS</p> <p>61-53700-20 MD37776 92 Ø 1,55 mm MLS</p> 	<p>14-55015-01 MD040514 (18x)</p> 	<p>15-52244-02 MD050312 +MD050536 +MD000523 (3x)</p> 	<p>12-52906-01 MD197467 (8x)</p> <p>70-52906-00 MD197467</p> <p>8x</p> 	<p>71-53732-00  </p> <p>MR188679</p> 	<p>70-31414-10</p> 	<p>81-53279-10 </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-53322-10 </p> <p>MD343564 80x96 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 	
	<p>2,5 4D56-T</p>	<p>85 kW (115 PS)</p>	<p>PAJERO TDI PAJERO TDI</p>					<p>61-53700-00 MD37774 92 Ø 1,45 mm MLS</p> <p>61-53700-10 MD37775 92 Ø 1,5 mm MLS</p> <p>61-53700-20 MD37776 92 Ø 1,55 mm MLS</p> 	<p>14-55015-01 MD040514 (18x)</p> 	<p>15-52244-02 MD050312 +MD050536 +MD000523 (3x)</p> 	<p>12-52906-01 MD197467 (8x)</p> <p>70-52906-00 MD197467</p> <p>8x</p> 	<p>70-31414-10</p> 	<p>81-53279-10 </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-53322-10 </p> <p>MD343564 80x96 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 		

MITSUBISHI































































Ltr.  2,5 4D56-T 85-98 kW (115-133 PS) PAJERO TD  12/99 

				<p>61-52252-20 1005B426 92,5 Ø 1,5 mm </p> <p>61-52252-30 1005B427 92,5 Ø 1,55 mm </p> <p>61-52252-40 1005B428 92,5 Ø 1,6 mm </p>  <p>61-53700-00 MD377774 92 Ø 1,45 mm MLS</p> <p>61-53700-10 MD377775 92 Ø 1,5 mm MLS </p> <p>61-53700-20 MD377776 92 Ø 1,55 mm MLS </p> 	<p>14-55015-01 MD040514 (18x)</p> 	<p>15-52244-02 MD050312 +MD050536 +MD000523 (3x)</p> 	<p>12-52906-01 MD197467 (8x)</p>  <p>70-52906-00 MD197467 8x</p> 	<p>71-53732-00  </p> <p>MR188679</p> 	<p>70-31414-10</p> 	<p>81-53279-10 K </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-53322-10 K </p> <p>MD343564 80x96 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 
--	--	---	--	--	--	---	--	---	---	---













































































2,5 4D56-TD 73 kW (99 PS) L 200 TD PAJERO TD 12/90-12/07

<p>01-52252-03 1000A901</p> 	<p>02-52252-03 1000A915</p> 	<p>04-10236-01 </p> 	<p>61-52252-10 1005B425 92,5 Ø 1,45 mm </p> <p>61-52252-20 1005B426 92,5 Ø 1,5 mm </p> <p>61-52252-30 1005B427 92,5 Ø 1,55 mm </p> <p>61-52252-40 1005B428 92,5 Ø 1,6 mm </p> 	<p>14-55015-01 MD040514 (18x)</p> 	<p>15-52244-02 MD050312 +MD050536 +MD000523 (3x)</p> 	<p>12-52906-01 MD197467 (8x)</p>  <p>70-52906-00 MD197467 8x</p> 	<p>71-53732-00  </p> <p>MR188679</p> 	<p>70-31414-10</p> 	<p>81-53279-10 K </p> <p>MD343563 44x60 A SL RD FPM</p>  <p>81-53322-10 K </p> <p>MD343564 80x96 A SL LD FPM</p>  <p>81-53246-00 N</p> <p>1052A366 35x50 A SL RD FPM</p> 
---	---	--	--	---	---	--	---	---	---













































MITSUBISHI

<p>Ltr.   </p>	<p>2,5 6A13 6G73 118-125 kW (160-170 PS) GALANT V6 11/92-10/04</p>											
<p>2,5 6A13 6G73 118-125 kW (160-170 PS) GALANT V6 11/92-10/04</p>	<p>01-53250-01 MD975563</p> 	<p>02-53250-01 MD975562</p> 			<p>61-53250-00 2x MD333227 82 Ø MLS</p> 		<p>15-53187-01 2x MD173371</p> 	<p>12-52829-03 MD184303 (24x)</p> 	<p>71-53189-00  2x MD327788</p>  <p>71-53188-00  2x MR281718</p> 	<p>70-31414-10 </p> 	<p>81-53254-00  K</p> <p>MD168055 37x50 A SL RD MVQ</p>  <p>81-53331-00  K</p> <p>MD150161 85x103 A SL LD MVQ</p>  <p>81-53246-00 N 1052A366 35x50 A SL RD FPM</p> 	
<p>2,6 G54B T/C 4G54 76-114 kW (103-155 PS) PAJERO STARION 01/83-11/90</p>	<p>01-52485-01 MD997458</p> 	<p>02-52485-01 MD997457</p> 			<p>61-52485-00 MD115646 93 Ø</p> 		<p>15-52236-01</p> 	<p>12-52906-01 MD197467 (8x)</p>  <p>70-52906-00 MD197467</p> 	<p>71-52464-00  K MD024628</p>  <p>71-52482-00  K MD102683</p> 	<p>71-52462-00 MD149392</p> 	<p>81-53322-10  K</p> <p>MD343564 80x96 A SL LD FPM</p> 	
<p>2,8 4M40-A 71 kW (97 PS) PAJERO D 11/93-07/97</p>					<p>61-52945-10 ME200751 96 Ø 1,3 mm </p> <p>61-52945-20 ME200752 96 Ø 1,35 mm </p> <p>61-52945-30 ME200753 96 Ø 1,4 mm </p> <p>61-52945-40 ME200754 96 Ø 1,45 mm </p> 	<p>14-55049-01 ME200426 (14x) +ME200848 (2x) +ME200427 (4x)</p> 	<p>15-52898-02 ME200403 +ME11282 (2x) +ME200269 +ME200270</p> 	<p>12-52906-01 MD197467 (8x)</p>  <p>70-52906-00 MD197467</p> 	<p>71-52903-00  K 4x ME200285</p>  <p>71-53018-00  K 4x ME202145</p> 	<p>70-31414-10 </p> 	<p>81-53289-00  K</p> <p>ME200028 52x74 A SL OD NBR</p>  <p>81-53346-00  K</p> <p>ME200012 92,5x114/120 A SL LD NBR</p> 	

MITSUBISHI























































<p>Ltr.  2,8 4M40-T</p> <p> 80-87 kW (109-118 PS) PAJERO TD</p> <p> 1 06/02</p>	 <p>01-52898-02 ME994149</p> 	 <p>02-52898-02</p> 		 <p>04-10240-01 </p> 	 <p>61-52945-10 ME200751 96 Ø 1,3 mm </p> <p>61-52945-20 ME200752 96 Ø 1,35 mm </p> <p>61-52945-30 ME200753 96 Ø 1,4 mm </p> <p>61-52945-40 ME200754 96 Ø 1,45 mm </p> 	 <p>14-55049-01 ME200426 (14x) +ME200848 (2x) +ME200427 (4x)</p> 	 <p>15-52898-02 ME200403 +ME011282 (2x) +ME200269 +ME200270</p> 	 <p>12-53987-01 ME200524 (8x)</p>  <p>70-53987-00 ME200524</p> 	 <p>71-52903-00  4x ME200285</p>  <p>71-52904-00  4x ME201356</p> 	 <p>70-31414-10</p> 	 <p>81-53606-00  ME202850 50x74</p>  <p>81-53607-00  ME202851 94,5x114</p> 
<p>2,8 4M40-T</p> <p>92-103 kW (125-140 PS) PAJERO D PAJERO TD</p> <p>11/93-10/99</p>	<p>01-52898-01 ME994141  ⇒ 04/96</p>  <p>01-52898-02 ME994148  05/96→</p> 	<p>02-52898-01  ⇒ 04/96</p>  <p>02-52898-02  05/96→</p> 		<p>04-10240-01 </p> 	<p>61-52945-10 ME200751 96 Ø 1,3 mm </p> <p>61-52945-20 ME200752 96 Ø 1,35 mm </p> <p>61-52945-30 ME200753 96 Ø 1,4 mm </p> <p>61-52945-40 ME200754 96 Ø 1,45 mm </p> 	<p>14-55049-01 ME200426 (14x) +ME200848 (2x) +ME200427 (4x)</p> 	<p>15-52898-02 ME200403 +ME011282 (2x) +ME200269 +ME200270</p> 	<p>12-53987-01 ME200524 (8x)</p>  <p>70-53987-00 ME200524</p> 	<p>71-52903-00  4x ME200285</p>  <p>71-53018-00  4x ME202145  ⇒ 04/96</p>  <p>71-52904-00  4x ME201356  05/96→</p> 	<p>70-31414-10</p> 	<p>81-53289-00  ME200028 52x74 A SL LD NBR  ⇒ 04/96</p>  <p>81-53606-00  ME202850 50x74  05/96→</p>  <p>81-53346-00  ME200012 92,5x114/120 A SL LD NBR  ⇒ 04/96</p>  <p>81-53607-00  ME202851 94,5x114  05/96→</p> 

MITSUBISHI														
Ltr.														
3,0 6G72 (DOHC 24V)	140-151 kW (190-205 PS)	09/89-09/02	DEBONAIR DIAMANTE SIGMA V6	01-53310-01 MD997670 	02-53310-01 MD997669 			61-53310-00 2x MD199239 92 Ø 1,3 mm MLS 		15-53399-01 2x MD186786 +MD186787 (3x) 	12-53396-01 2x MD306079 (12x) +MD307343 (12x) 	71-53397-00 2x MD164701 71-53398-00 2x MD168115 	70-31414-10 	81-53254-00 K ↔ MD168055 37x50 A SL RD MVQ 81-53343-00 K ↔ MD372251 91x111 A SL LD MVQ 81-53394-00 N 4x MD177097 30x42 A SL OD MVQ
3,0 6G72 (DOHC 24V)	163-210 kW (222-286 PS)	06/89-12/00	GTO Coupe 3000 GT	01-53310-01 MD997670 	02-53310-01 MD997669 			61-53310-00 2x MD199239 92 Ø 1,3 mm MLS 	14-55063-01 2x MD069599 (8x) 	15-53399-01 2x MD186786 +MD186787 (3x) 	12-53396-01 2x MD306079 (12x) +MD307343 (12x) 	71-53397-00 2x MD164701 71-53398-00 2x MD168115 	70-31414-10 	81-53254-00 K ↔ MD168055 37x50 A SL RD MVQ 81-53343-00 K ↔ MD372251 91x111 A SL LD MVQ 81-53394-00 N 4x MD177097 30x42 A SL OD MVQ

MITSUBISHI															
Ltr. 															
3,0 6G72 (SOHC 24V)	128-135 kW (174-184 PS)	PAJERO	01/07						<p>61-10196-00 MD320044 92 Ø 0,35 mm MLS</p> 	<p>71-16966-00 MD303148</p> 	<p>70-54169-00 MD184303</p> 	<p>71-16964-00  2x MR561678</p> 	<p>70-31414-10</p> 	<p>81-10431-00  MD372249 37x50 A SL RD FPM</p>  <p>81-53343-00  MD372251 91x111 A SL LD MVQ</p>  <p>81-53246-00 N 2x 1052A366 35x50 A SL RD FPM</p> 	
3,0 6G72 (SOHC 24V)	129 kW (175 PS)	PAJERO	09/96-12/01						<p>14-55063-01 MD065959 (8x) 2x</p> 		<p>12-52829-03 MD184303 (24x)</p> 	<p>70-54169-00 MD184303 24x</p> 	<p>70-31414-10</p> 	<p>81-53343-00  MD372251 91x111 A SL LD MVQ</p>  <p>81-53246-00 N 2x 1052A366 35x50 A SL RD FPM</p> 	
3,0 6G72 (SOHC 24V)	130-133 kW (177-181 PS)	PAJERO PAJERO V6	06/94-04/00					<p>61-53310-00 2x MD199239 92 Ø 1,3 mm MLS</p> 	<p>71-16966-00 MD303148</p> 	<p>12-52829-03 MD184303 (24x)</p> 	<p>71-16964-00  2x MR561678</p> <p>71-16965-00  2x MR281721</p> 	<p>70-31414-10</p> 	<p>81-10431-00  MD372249 37x50 A SL RD FPM</p>  <p>81-53343-00  MD372251 91x111 A SL LD MVQ</p>  <p>81-53246-00 N 2x 1052A366 35x50 A SL RD FPM</p> 		

MITSUBISHI															
Ltr.															
3,0	6G72 (SOHC 24V)	152 kW (207 PS)	GALANT	01/99-12/03											
					61-10196-00 2x MD320044 92 Ø 0,35 mm MLS 					71-16966-00 2x MD303148 	12-52829-03 24x MD184303 (24x) 70-54169-00 24x MD184303 	70-31414-10 	81-53254-00 K↔ MD168055 37x50 A SL RD MVO 		
3,2	4M41	118-129 kW (160-175 PS)	PAJERO DI-D	04/00	01-53739-01 ME933318 	02-53739-01 				61-53710-00 ME204037 99,5 Ø 0,5 mm MLS 1 61-53710-10 ME204038 99,5 Ø 0,55 mm MLS 2 61-53710-20 ME204039 99,5 Ø 0,6 mm MLS 3 61-53710-30 ME204040 99,5 Ø 0,65 mm MLS 4 	71-53739-00 ME192209 	12-52718-02 MD115472 (16x) 70-52718-00 16x MD115472 	71-53741-00 ME203212 11-53742-01 ME203114 (4x) 	71-53743-00 ME201756 	81-53606-00 K↔ ME202850 50x74 81-53744-00 K↔ ME203250 90,5x114
3,3	4D30	64 kW (87 PS)				02-52490-01 ME999278 HS 				61-52490-00 ME011045 102,7 Ø MLS 	71-52486-00 ME011417 	12-53034-01 ME215092 (8x) 	71-52483-00 4x ME013536 	71-52484-00 ME014009 	
3,3	4D31T	86 kW (117 PS)			01-52490-02 ME999663 	02-52490-02 ME999663 HS 				61-52490-00 ME011045 102,7 Ø MLS 	71-52487-00 ME011279 	12-53034-01 ME215092 (8x) 	71-52483-00 4x ME013536 	71-52484-00 ME014009 	

MITSUBISHI

<p>Ltr.  3,5 VQ35HR 275 kW (374 PS) PROUDIA  07/12 </p>					<p>61-53675-00 R 96 Ø 0,58 mm MLS</p>  <p>61-53680-00 L 96 Ø 0,58 mm MLS</p> 		<p>15-53681-01 L</p>  <p>15-53709-01 R</p> 	<p>12-52738-02</p> 	<p>71-53711-00 L  2x</p>  <p>71-53712-00 L  2x</p>  <p>71-53713-00  2x</p> 	<p>70-31414-10</p> 	<p>81-53661-00 K </p> <p>48x60 RD MVQ</p> 
<p>3,5 6G74 (DOHC 24V) 149-162 kW (203-220 PS) PAJERO PAJERO V6 GDI 04/00-01/07</p>	<p>01-10300-01 MD977502</p> 	<p>02-10300-01 MD977501</p> 			<p>61-10300-00 2x MD348974 94,5 Ø 0,35 mm MLS</p> 	<p>14-55063-01 2x MD065959 (8x)</p> 	<p>71-13255-00 2x MD349844</p> 	<p>12-53396-01 MD306079 (12x) +MD307343 (12x)</p> 	<p>71-13256-00 L  2x MD366659</p>  <p>71-13257-00  2x MR404669</p> 	<p>70-31414-10</p> 	<p>81-10431-00 K </p> <p>MD372249 37x50 A SL RD FPM</p>  <p>81-53343-00 K </p> <p>MD372251 91x111 A SL LD MVQ</p>  <p>81-10506-00 N 4x MD152603 30x42 ACM</p> 
<p>3,8 6G75 172-184 kW (234-250 PS) PAJERO PAJERO V6 10/06</p>					<p>61-10741-00 L 1005B047 96 Ø 0,35 mm MLS</p>  <p>61-10742-00 R 1005B046 96 Ø 0,35 mm MLS</p> 	<p>14-55063-01 2x MD065959 (8x)</p> 	<p>71-17239-00 2x MN137773</p> 	<p>12-52829-03 MD184303 (24x)</p>  <p>70-54169-00 24x MD184303</p> 	<p>71-17240-00 L  2x 1540A194</p>  <p>71-16965-00  2x MR281721</p> 	<p>70-31414-10</p> 	<p>81-10431-00 K </p> <p>MD372249 37x50 A SL RD FPM</p>  <p>81-53343-00 K </p> <p>MD372251 91x111 A SL LD MVQ</p>  <p>81-53246-00 N 2x 1052A366 35x50 A SL RD FPM</p> 

Haftungsausschluss

(für Katalog)

Alle Angaben in unserem Katalog wurden von uns sorgfältig geprüft, sind jedoch unverbindlich. Ersatzansprüche wegen Katalogangaben werden von uns nicht anerkannt. Der Käufer ist selbst verpflichtet, zu prüfen, ob unsere Teile für seine Zwecke geeignet sind. In allen Zweifelsfällen sollte Rücksprache mit unserem technischen Kundendienst erfolgen **Tel. +49 731 7046 999**.

Technische Weiterentwicklungen oder Änderungen bleiben vorbehalten, soweit damit keine Nachteile für den Kunden verbunden sind.

Angaben, Namens- und Markenzeichen, Beschreibungen, Nummern von Fahrzeugnummern und Herstellerzeichen, Original-Ersatzteilnummern der Fahrzeug- und Motorenhersteller u. a. sind ausschließlich für interne Zwecke gedacht. Solche Kennzeichnungen dürfen Fahrzeugbesitzern gegenüber nicht verwendet werden.

Wir weisen ausdrücklich darauf hin, dass alle von uns gelieferten Teile von geschultem Fachpersonal einzubauen sind. Reinz haftet für Fehler in diesem Katalog nur, wenn diese für den Kunden nicht offenbar erkennbar sind sowie nur bei Vorsatz und grober Fahrlässigkeit von Reinz, eines Vertreters oder eines Erfüllungsgehilfen. Dieser Haftungsausschluss gilt nicht im Rahmen

des Anwendungsbereichs des Produkthaftungsgesetzes und nicht bei Verletzung von Körper, Leben und Gesundheit, sowie bei der Verletzung von sog. Kardinalpflichten. Darüber hinaus ist unsere Haftung für Schäden, insbesondere für Personen-, Sach- oder Vermögensschäden, die unmittelbar oder mittelbar im Zusammenhang mit der Nutzung dieses Kataloges auftreten, sowie für nicht voraussehbare Schäden ausgeschlossen.

Reinz ist Inhaber aller Schutzrechte an den in diesem Katalog gespeicherten Daten. Kopie, Nachdruck, ganze oder teilweise Übernahme der Inhalte und Vervielfältigung, auch auszugsweise, ist nur mit unserer vorheriger schriftlicher Zustimmung sowie mit unserem Urheberrechtsvermerk zulässig.

Für Bestellungen, welche ab dem Erscheinungsdatum eines neuen Katalogs getätigt werden, sind alleine die Angaben des neuen Katalogs maßgeblich. Auf Angaben im Vorkatalog kann bei Neubestellungen nicht mehr zurückgegriffen werden.

Sofern Sie noch Fragen haben, bitten wir Sie, sich mit uns in Verbindung zu setzen.

VictorReinz.com/AGB

Exclusion of Liability

(for catalog)

All details in our catalog have been thoroughly checked by us but are however not binding. Right to damages on account of catalog details will not be recognized. The purchaser is obliged to check if our parts are suitable for their use. In all doubtful cases, the purchaser should consult our technical customer service under **+49 731 7046 999**.

We reserve the right to further technical developments or changes as long as no disadvantage for the customer results.

Details, name and trademarks, descriptions, numbers from vehicle numbers and manufacturer symbols, original vehicle replacement part numbers and engine manufacturer etc. are solely for internal use. Such labels must not be used with vehicle owners.

We specifically point out that all parts supplied by us must be assembled by trained specialists.

Reinz is liable for mistakes in this catalog only when they are not clearly recognizable for the customer, as well as by intent or gross negligence on the part of Reinz, its representative or vicarious agent. This exclusion of liability does not apply within the framework of the field of

application of the product liability laws and not by bodily harm, life and health, as well as by violation of cardinal duties. In addition, our liability for damages, especially personal, property or financial damages that occur directly or indirectly as a result of the use of this catalog, as well as non-foreseeable damages are excluded.

Reinz is the owner of all patent rights on the data stored in this catalog. Copies, reprints, whole or partial takeover of the contents and duplication even in excerpts are only permissible with our prior written approval, as well as with our copyright note.

For orders placed after the publication date of a new catalog, only the details in the new catalog are binding and no fall back to details in the previous catalog is possible.

In case you have further questions, do not hesitate to contact us.

VictorReinz.com/AGB

VictorReinz.com

reinz.info@dana.com

Technical Hotline +49 (0)731 7046-9 99

REINZ-Dichtungs-GmbH

Reinzstrasse 3-7
89233 Neu-Ulm
Germany
+49 (0)731 7046-0

VICTOR REINZ[®]

