


VICTOR REINZ®



SUBARU
Q3 / 2023



VictorReinz.com/online-catalog

Victor Reinz®

at a Glance



Online Catalog

VictorReinz.com/online-catalog



Newsletter

VictorReinz.com/EN/News/Newsletter.aspx?region



Youtube

www.youtube.com/user/VictorReinzSealingEN



Catalog News

VictorReinz.com/news



Technical Service Information

VictorReinz.com/tsi



Facebook

www.facebook.com/VictorReinzParts



Just seal it!

VictorReinz.com/jsi



Technical Datasheet

VictorReinz.com/jsi-datasheet



LinkedIn

www.linkedin.com/showcase/victor-reinz-emea




Safety Datasheet

VictorReinz.com/jsi-datasheet




Homepage


VictorReinz.com



[VictorReinz.com/catalog-info](https://www.victorreinz.com/catalog-info)



[VictorReinz.com/catalog-how-to-use](https://www.victorreinz.com/catalog-how-to-use)



SUBARU



0-9

1KR-FE	6
1ND-TV	8
1NR-FE	7
1NR-FKE	7

E

EA65	6
EA71	9
EA82	12-13
EE20	14
EE20Z	14-16
EF10	5
EF12	6
EJ16	9
EJ161	10
EJ16E	9
EJ18	13
EJ18 SPI	13
EJ18E	13
EJ20	16
EJ20 EMPI	16
EJ201	18
EJ202	18
EJ204	19-21
EJ205	22-23
EJ207	23-24
EJ208	24
EJ20E	17
EJ20G	17
EJ20J	17
EJ22 EMPI	30
EJ25	31-33
EJ251	34
EJ253	35-36
EJ255	36-38
EJ257	39-40
EJ25D	34
EK23	5
EK42	5
EL15	8
EL154	8
EZ30	43
EZ36D	43



F


































































FA20	25
FA20D	26
FA20E	25
FA20F	25
FB16	10
FB16A	11
FB16B	12
FB20	26
FB20A	27
FB20B	26-27
FB20C	28
FB20D	28
FB20W	29
FB20X	30
FB25	40-42
FB25A	42
FB25B	42
FB25C	42
FB25D	42

M



M13A	6
M15A	9







































SUBARU														
0,5	EK23	23 kW (31 PS)	REX	08/77-06/87	01-52525-01 49712-3051 	02-52525-01 49712-3051 HS 			61-52525-00 41230-5700 78 Ø 			12-53043-01 41277-5400 (2x) +41279-1300 (2x) 		
0,7	EK42	27 kW (37 PS)	REX	08/82-06/89	01-52525-01 49712-3051 	02-52525-01 49712-3051 HS 			61-52525-00 41230-5700 78 Ø 			12-53043-01 41277-5400 (2x) +41279-1300 (2x) 		
1,0	EF10	37 kW (50 PS)	JUSTY	05/87-10/95	01-52530-02 49712-3058 	02-52530-02 49712-3058 HS 			61-52530-00 41230-6202 79,5 Ø 	71-52526-00 13294-KA061 	12-53043-02 41277-5400 (3x) +41279-1300 (3x) 	71-52527-00 14038-KA050 	71-52524-00 41160-5500 	81-53227-00 30x46 A SL RD MVQ 81-53266-00 38,5x53 A SL OD
1,0	EF10	37-40 kW (50-54 PS)	JUSTY LIBERO	01/83-12/90	01-52530-01 49712-3057 ⇒ 06/85 01-52530-02 49712-3058 07/85→ 	02-52530-01 49712-3057 HS ⇒ 06/85 02-52530-02 49712-3058 HS 07/85→ 			61-52530-00 41230-6202 79,5 Ø 	71-52523-00 41260-5600 ⇒ 06/85 71-52526-00 13294-KA061 07/85→ 	12-53043-02 41277-5400 (3x) +41279-1300 (3x) 	71-52527-00 14038-KA050 07/85→ 	71-52524-00 41160-5500 	81-53227-00 30x46 A SL RD MVQ 81-53266-00 38,5x53 A SL OD

SUBARU




















<p>Ltr. </p>	<p>1,0 1KR-FE</p>	<p>51 kW (69 PS)</p>	<p>JUSTY</p>	<p>01/07</p>											
<p>1,2 1KR-FE</p>	<p>51 kW (69 PS)</p>	<p>JUSTY</p>	<p>01/07</p>	<p>01-53425-01</p> 	<p>02-53425-01</p> 			<p>61-53425-00 72 Ø 0,5 mm MLS</p> <p>61-53425-10  72 Ø 0,8 mm MLS</p> 	<p>14-32366-01</p> 	<p>71-53503-00</p> 	<p>12-53507-01</p> 	<p>71-53504-00 </p>  <p>71-53506-00 </p> 	<p>70-31414-10</p> 	<p>81-34146-00 </p> <p>38x50 A SL RD FPM</p>  <p>81-53509-00 </p> <p>74x89 A SL LD MVQ</p> 	
<p>1,2 EF12</p>	<p>38-50 kW (52-68 PS)</p>	<p>JUSTY LIBERO</p>	<p>06/86-02/00</p>	<p>01-52535-02 49712-3013</p> 	<p>02-52535-02 49712-3013 HS</p> 			<p>61-52535-00 11044-KA030 79,5 Ø</p> 		<p>71-52528-00 13294-KA070</p> 	<p>12-53043-02 41277-5400 (3x) +41279-1300 (3x)</p> 	<p>71-52527-00 </p> <p>14038-KA050</p> 	<p>71-52524-00 41160-5500</p> 	<p>81-53227-00 </p> <p>30x46 A SL RD MVQ</p>  <p>81-53266-00 N</p> <p>38,5x53 A SL OD</p> 	
<p>1,3 EA65</p>	<p>45-48 kW (61-65 PS)</p>	<p>LEONE</p>	<p>03/79-09/91</p>	<p>01-52532-01 49712-3053</p> 	<p>02-52532-01</p> 			<p>61-52532-00 2x 11044-KA410 86,8 Ø</p> 	<p>71-52343-00 2x 81260-8600</p> 	<p>12-53039-01 81277-7000 (4x)</p> 	<p>71-52539-00 </p> <p>14035-AA000 2x</p>  <p>71-52341-00 </p> <p>64400-3200 2x</p> 	<p>71-52342-00 81160-6100</p> 	<p>81-53263-00 </p> <p>80673-8040 38x55 A SL RD NBR</p> 		
<p>1,3 M13A</p>	<p>69 kW (94 PS)</p>	<p>JUSTY</p>	<p>09/03</p>		<p>02-53640-03</p> 			<p>61-53640-00 11141-69G03 79 Ø MLS</p> 		<p>71-53698-00 11189-69E0</p> 	<p>12-52939-01 09289-05012 (16x)</p>  <p>70-52939-00 16x 09289-05012</p> 	<p>71-53696-00 </p> <p>13119-86G00</p>  <p>71-53697-00 </p> <p>14140-69G01</p> 	<p>70-31414-10</p> 	<p>81-53699-00 </p> <p>09283-41001 41x53 A SL RD FPM</p>  <p>81-53701-00 </p> <p>83x103 FPM</p> 	

SUBARU
































































Ltr.  1,3 1NR-FE 70-73 kW (95-99 PS) TREZIA  11/10 

										
<p>01-54030-01</p> 	<p>02-54030-01</p> 			<p>61-54030-00 0,5 mm MLS</p> 	<p>14-32328-01</p> 	<p>71-54088-00</p> 	<p>12-54024-01</p>  <p>70-54024-00 ES 8x</p>  <p>70-54026-00 AS 8x</p> 	<p>71-54089-00 </p>  <p>71-54091-00 </p> 	<p>70-31414-10</p> 	<p>81-53218-00  </p> <p>25,5x37,5 A SL RD NBR</p>  <p>81-54107-00  </p> <p>77,5x171,5 A SL LD FPM</p>  <p>81-54108-00   </p> <p>157,5x171,5 A SL FPM</p>  <p>81-54109-00   </p> <p>138x152,6 AB SL LD FPM</p> 

1,3 1NR-FKE 73 kW (99 PS) TREZIA 03/11

<p>01-10997-02</p> 	<p>02-10997-02</p> 			<p>61-10747-00 0,5 mm MLS</p> 	<p>14-32328-01</p> 	<p>71-17321-00</p> 	<p>12-54024-01</p>  <p>70-54024-00 ES 8x</p>  <p>70-54026-00 AS 8x</p> 	<p>71-54089-00 </p>  <p>71-54091-00 </p> 	<p>70-31414-10</p> 	<p>81-10420-00  </p> <p>36x48 A SL RD FPM</p>  <p>81-10421-00  </p> <p>78x105,5 A SL LD FPM</p> 
--	--	--	--	---	--	--	---	---	--	---

































SUBARU

<p>Ltr.  1,4 1ND-TV 66 kW (90 PS) TREZIA D  03/11 </p>	 01-13166-01 	 02-13166-01 			 61-10291-00 ✕ 74,4 Ø 1  MLS 61-10291-10 ✕ 74,4 Ø 2  MLS 61-10291-20 ✕ 74,4 Ø 3  MLS 61-10291-30 ✕ 74,4 Ø 4  MLS 61-10291-40 ✕ 74,4 Ø 5  MLS 	 14-13174-01 	 71-13166-00 	 12-53854-02  70-53854-00 8x 	 71-13187-00  	 70-31414-10 	 81-35144-00  40x52 A SL RD FPM  81-10501-00  75x110 A SL LD FPM 
<p>1,5 EL15 74-85 kW (101-116 PS) IMPREZA 06/01  [NEW]</p>	 01-10113-01 10105-AB040	 02-10113-01			 61-10113-00 2x 11044-AA700 101,3 Ø MLS 	 14-11012-01 2x 11095-AA042 (6x) 	 15-53998-01  13270-AA190 +13293-AA051 (2x)  15-53999-01  13272-AA140 +13293-AA051 (2x) 	 12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)  70-53989-00 ES 8x 13207-AA120  70-53991-00 AS 8x 13211-AA110 	 71-53941-00  2x 14035-AA421 	 70-31414-10 	 81-53918-00  80673-3030 33x49 A SL RD FPM  81-53333-00  80678-6040 86x103 A SL LD MVQ  81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM  81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM 

































SUBARU

Ltr.	M15A	73 kW (99 PS)	JUSTY	09/03											
1,5	M15A	73 kW (99 PS)	JUSTY	09/03		02-53640-03 			61-53640-00 11141-69G03 79 Ø MLS 		71-53698-00 11189-69E0 	12-52939-01 09289-05012 (16x) 16x 70-52939-00 09289-05012 	71-53696-00 I 13119-86G00 71-53697-00 I 14140-69G01 	70-31414-10 	81-53699-00 K 09283-41001 41x53 A SL RD FPM 81-53701-00 K 83x103 FPM
1,6	EA71	52-63 kW (71-86 PS)	LEONE MV	06/78-12/94	01-52537-01 49712-3000 	02-52537-01 49712-3000 HS 			61-52537-00 41230-7122 94 Ø 		71-52343-00 2x 81260-8600 	12-53039-01 81277-7000 (4x) 4x	71-52342-00 2x 14035-AA000 71-52341-00 2x 64400-3200 	71-52342-00 81160-6100 	
1,6	EJ16	66-70 kW (90-95 PS)	IMPREZA LEGACY	05/89-09/06	01-52990-01 10105-AA130 	02-52990-01 			61-52990-00 2x 11044-AA120 89 Ø 		71-52951-00 2x 13294-AA010 	12-52829-01 8x	71-52942-00 I 2x 14035-AA290 71-52943-00 I 2x 71-52944-00 I 2x 71-52938-10 I 2x 44616-AA290 	71-52946-00 	81-53333-00 K 80678-6040 86x103 A SL LD MVQ 81-53239-00 N 80673-2150 32x45 A SL RD ACM
1,6	EJ16E	66 kW (90 PS)	IMPREZA	01/93-12/00					61-52990-00 2x 11044-AA120 89 Ø 	14-11006-01 11095-AA123 (8x) +11095-AA141 (4x) 	71-52951-00 2x 13294-AA010 	12-53919-01 13207-AA050 (8x) +13211-AA050 (8x) 70-53989-00 ES 8x 13207-AA120 70-53991-00 AS 8x 13211-AA110 	71-52942-00 I 2x 14035-AA290 71-52938-10 I 2x 44616-AA290 		81-53918-00 K 80673-3030 33x49 A SL RD FPM 81-53333-00 K 80678-6040 86x103 A SL LD MVQ 81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM

SUBARU















































Ltr.	Engine	Power	Model	Year	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11					
1,6	EJ161	66-88 kW (90-120 PS)	IMPREZA	01/93-06/09	<p>01-10254-01 10105AA280</p> 	<p>02-10254-01</p> 			<p>61-10254-00 2x 11044AA573 89,5 Ø 0,5 mm MLS</p> 	<p>14-11006-01 11095-AA123 (8x) +11095-AA141 (4x)</p> 	<p>71-53988-00 2x 13294-AA053</p> 	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p> 	<p>71-53989-00 ES 8x 13207-AA120</p> 	<p>71-53991-00 AS 8x 13211-AA110</p> 	<p>71-53982-00 2x 14035-AA383</p> 	<p>71-52938-10 2x 44616-AA290</p> 	<p>70-31414-10</p> 	<p>81-53918-00 K 80673-3030 33x49 A SL RD FPM</p> 	<p>81-53333-00 K 80678-8040 86x103 A SL LD MVQ</p> 	<p>81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM</p> 
1,6	FB16	125 kW (170 PS)	LEVORG	09/15	<p>01-11325-01 10105-AB770</p> 	<p>02-11325-01</p> 			<p>61-11325-00 R 11044-AA880 81,8 Ø 0,6 mm MLS</p> 	<p>14-11012-01 2x 11095-AA042 (6x)</p> 	<p>15-10675-01 R 13270-AA250 +10966-AA040 (2x)</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p> 	<p>71-20004-00 4x 14035-AA700</p> 	<p>71-16042-00 2x 14035-AA570</p> 	<p>71-52938-10 2x 44616-AA290</p> 	<p>70-31414-10</p> 	<p>81-53387-00 K 80675-0070 50x62 RD</p> 	<p>81-10384-00 K 80679-2010 92x109 A SL LD FPM</p> 		
									<p>61-11326-00 L 10944-AA170 81,8 Ø 0,6 mm MLS</p> 		<p>15-20003-01 L 13272-AA270 +10966-AA040 (2x)</p> 	<p>70-10695-00 AS 8x 13211-AA100</p> 	<p>70-11562-00 ES 8x 13207-AA110</p> 							

SUBARU


Ltr.	Engine	Power	Model	Year	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11		
1,6	FB16A	84 kW (114 PS)	IMPREZA XV	03/12	<p>01-10257-01 10105-AB490</p> 	<p>02-10257-01</p> 			<p>61-10257-00 L 10944-AA090 79,8 Ø 0,5 mm MLS</p>  <p>61-10258-00 R 11044-AA800 79,8 Ø 0,5 mm MLS</p> 	<p>14-11012-01 11095-AA042 (6x)</p> 	<p>2x</p>	<p>71-10693-00 R 13270-AA240</p>  <p>71-10694-00 L 13272-AA170</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p>  <p>70-10695-00 AS 13211-AA100</p>  <p>8x</p> <p>70-11562-00 ES 13207-AA110</p>  <p>8x</p>	<p>71-10697-00 L 14035-AA580</p>  <p>71-52938-10 44616-AA290</p> 	<p>2x</p>	<p>70-31414-10</p> 	<p>81-53387-00 K 80675-0070 50x62 RD</p>  <p>81-10384-00 K 80679-2010 92x109 A SL LD FPM</p> 
1,6	FB16A	84-85 kW (114-116 PS)	IMPREZA XV	10/16	<p>01-11325-01 10105-AB770</p> 	<p>02-11325-01</p> 			<p>61-11325-00 R 11044-AA880 81,8 Ø 0,6 mm MLS</p>  <p>61-11326-00 L 10944-AA170 81,8 Ø 0,6 mm MLS</p> 	<p>14-11012-01 11095-AA042 (6x)</p> 	<p>2x</p>	<p>15-10675-01 R 13270-AA250 +10966-AA040 (2x)</p>  <p>15-20003-01 L 13272-AA270 +10966-AA040 (2x)</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p>  <p>70-10695-00 AS 13211-AA100</p>  <p>8x</p> <p>70-11562-00 ES 13207-AA110</p>  <p>8x</p>	<p>71-20004-00 14035-AA700</p>  <p>71-52938-10 44616-AA290</p> 	<p>4x</p>	<p>70-31414-10</p> 	<p>81-53387-00 K 80675-0070 50x62 RD</p>  <p>81-10384-00 K 80679-2010 92x109 A SL LD FPM</p> 

SUBARU														
Ltr.														
1,6	FB16B	84-85 kW (114-115 PS)	03/12	01-10257-01 10105-AB490	02-10257-01			61-10257-00 L 10944-AA090 79,8 Ø 0,5 mm MLS	14-11012-01 11095-AA042 (6x)	2x 71-10693-00 R 13270-AA240	12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)	71-10697-00 L 14035-AA580	70-31414-10	81-53387-00 K 80675-0070 50x62 RD
								61-10258-00 R 11044-AA800 79,8 Ø 0,5 mm MLS		71-10694-00 L 13272-AA170		71-16042-00 L 14035-AA570		81-10384-00 K 80679-2010 92x109 A SL LD FPM
											71-52938-10 44616-AA290	71-10695-00 AS 13211-AA100		
											71-11562-00 ES 13207-AA110			
1,8	EA82	66-72 kW (90-98 PS)	11/84-09/94	01-52540-02 X1041-AA011	02-52540-02 X1041-AA011 HS			61-52540-00 11044-AA013 94,5 Ø		71-52533-00 R 13272-AA000	12-53043-03 41277-5400 (4x) +41279-1300(4x)	71-52539-00 L 14035-AA000	71-52536-00 11121-AA000	81-53261-00 K 80673-8070 38x59 A SL RD NBR
										71-52534-00 L 13270-AA000				81-53316-00 K 80677-6010 76x93 A SL LD MVQ
														81-53263-00 N 80673-8040 38x55 A SL RD NBR

SUBARU

Ltr.	EA82	66-77 kW (90-105 PS)	LEONE	06/85-07/87											
1,8	EA82	66-77 kW (90-105 PS)	LEONE	06/85-07/87	<p>01-52540-02 X1041-AA011</p> 	<p>02-52540-02 X1041-AA011 HS</p> 			<p>61-52540-00 2x 11044-AA013 94,5 Ø</p> 		<p>71-52533-00 R 13272-AA000</p>   <p>71-52534-00 L 13270-AA000</p> 	<p>12-53043-03 41277-5400 (4x) +41279-1300(4x)</p> 	<p>71-52538-00  2x 14035-AA011</p>  <p>71-52539-00  2x 14035-AA000</p> 	<p>71-52536-00 11121-AA000</p> 	<p>81-53261-00  80673-8070 38x59 A SL RD NBR</p>  <p>81-53316-00  80677-8010 76x93 A SL LD MVQ</p>  <p>81-53263-00 N 80673-8040 38x55 A SL RD NBR</p> 
1,8	EJ18 EJ18 SPI EJ18E	76-82 kW (103-112 PS)	IMPREZA LEGACY	01/89-12/00	<p>01-52990-01 10105-AA130</p> 	<p>02-52990-01</p> 			<p>61-52990-00 2x 11044-AA120 89 Ø</p> 		<p>71-52951-00 2x 13294-AA010</p> 	<p>12-52829-01</p> 	<p>71-52942-00  2x 14035-AA290</p>  <p>71-52943-00  2x</p>  <p>71-52944-00  2x</p>  <p>71-52938-10  2x 44616-AA290</p> 	<p>71-52946-00</p> 	<p>81-53333-00  80678-8040 86x103 A SL LD MVQ</p>  <p>81-53239-00  80673-2150 32x45 A SL RD ACM</p> 

SUBARU


Ltr.  2,0 EE20 EE20Z 80-110 kW (109-150 PS) FORESTER D IMPREZA IMPREZA D LEGACY D OUTBACK D XV D 01/09 




01-11014-01
10105-AB240


02-11014-01

61-10781-00 R
11044-AA740
86,5 Ø
0,95 mm
MLS 

61-10781-10 R
11044-AA730
86,5 Ø
1 mm
MLS 

61-10781-20 R
11044-AA750
86,5 Ø
1,05 mm
MLS 




61-10782-00 L
10944AA040
86,5 Ø
0,95 mm
MLS 

61-10782-10 L
10944AA030
86,5 Ø
1 mm
MLS 

61-10782-20 L
10944-AA050
86,5 Ø
1,05 mm
MLS 



14-17783-01
11095AA150 (6x) 

15-17784-01 R
13270AA220
+13294AA080 (2x)


15-17785-01 L
13272AA160
+13294AA080 (2x)


71-17784-00 R
13270AA220

71-17785-00 L
13272AA160


12-17789-01
13211-AA120 (8x)

70-17789-00
13211AA120

71-17791-00 L  4x

71-17792-00  2x

70-31414-10



81-10589-00 K 



81-53333-10 K 

806737010
37x52,5
A SL RD FPM

80678-8050
86x103
A SL LD FPM

SUBARU


Ltr.  2,0 EE20Z 108-110 kW (147-150 PS) FORESTER D LEGACY OUTBACK D  02/08-09/13  1




01-11014-01
10105-AB240


02-11014-01


61-10781-00 R
11044-AA740
86,5 Ø
0,95 mm
MLS  1


61-10781-10 R
11044-AA730
86,5 Ø
1 mm
MLS  2

61-10781-20 R
11044-AA750
86,5 Ø
1,05 mm
MLS  3



61-10782-00 L
10944AA040
86,5 Ø
0,95 mm
MLS  1

61-10782-10 L
10944AA030
86,5 Ø
1 mm
MLS  2

61-10782-20 L
10944-AA050
86,5 Ø
1,05 mm
MLS  3



14-17783-01
11095AA150 (6x)  2x


15-17784-01 R
13270AA220
+13294AA080 (2x)


15-17785-01 L
13272AA160
+13294AA080 (2x)

71-17784-00 R
13270AA220

71-17785-00 L
13272AA160


12-17789-01
13211-AA120 (8x)  2x

70-17789-00
13211AA120  16x

71-17792-00  2x

70-31414-10



81-10589-00 K 

81-53333-10 K 

81-10589-00 K


SUBARU


Ltr.  2,0 EE20Z 110 kW (150 PS) OUTBACK D 03/15



01-11099-01
10105-AB720


02-11099-01


61-10809-00 R
11044-AA850
86,5 Ø
0,95 mm
MLS 


61-10809-10 R
11044-AA840
86,5 Ø
1 mm
MLS 

61-10809-20 R
11044-AA860
86,5 Ø
1,05 mm
MLS 



61-10810-00 L
10944-AA140
86,5 Ø
0,95 mm
MLS 

61-10810-10 L
10944-AA130
86,5 Ø
1 mm
MLS 

61-10810-20
10944-AA150
86,5 Ø
1,05 mm
MLS 



14-17783-01
11095AA150 (6x) 2x

15-18161-01 R
13270-AA280
+13294-AA100 (2x)



15-18164-01 L
13272-AA230
+13294-AA100 (2x)



71-18161-00 R
13270-AA280




71-18164-00 L
13272-AA230



12-17789-01
13211-AA120 (8x) 2x

71-17791-00 L  4x
14035AA550

70-17789-00 16x
13211AA120

70-31414-10


71-17792-00  2x
44616AA080




01-52995-01
10105-AA070

02-52995-01

61-52995-00 2x
11044-AA364
93 Ø




71-52951-00 2x
13294-AA010




12-52829-01
14035-AA290


71-52942-00 L  2x
14035-AA290


71-52938-10  2x
44616-AA290



81-53333-00 K 
80678-6040
86x103
A SL LD MVQ


























































81-53239-00 N 
80673-2150
32x45
A SL RD ACM


















































SUBARU																	
2,0	EJ20E	85-103 kW (115-140 PS)	IMPREZA LEGACY	06/91-12/00	01-52995-01 10105-AA070 	02-52995-01 			61-52995-00 2x 11044-AA364 93 Ø 	14-11006-01 11095-AA123 (8x) +11095-AA141 (4x) 	71-52951-00 2x 13294-AA010 	12-52829-01 	71-52942-00 2x 14035-AA290 	71-52946-00 	81-53333-00 K 80678-6040 86x103 A SL LD MVQ 	81-53239-00 N 80673-2150 32x45 A SL RD ACM 	
2,0	EJ20G	155-184 kW (211-250 PS)	IMPREZA	10/93-12/00					14-11012-01 2x 11095-AA042 (6x) 			12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 	71-53921-00 2x 14035-AA281 	70-31414-10 	81-53918-00 K 80673-3030 33x49 A SL RD FPM 	81-53333-00 K 80678-6040 86x103 A SL LD MVQ 	81-53239-00 N 4x 80673-2150 32x45 A SL RD ACM
2,0	EJ20J	92 kW (125 PS)			01-52995-02 10105-AA190 	02-52995-02 		61-52995-00 2x 11044-AA364 93 Ø 		71-52951-00 2x 13294-AA010 	12-53919-01 13207-AA050 (8x) +13211-AA050 (8x) 	71-53914-00 4x 14035-AA350 	70-31414-10 	81-53918-00 K 80673-3030 33x49 A SL RD FPM 	81-53333-00 K 80678-6040 86x103 A SL LD MVQ 	81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM 	

SUBARU


























































<p>Ltr.  EJ201</p> <p>85-92 kW (115-125 PS)</p> <p>FORESTER IMPREZA LEGACY OUTBACK</p> <p>09/94-06/09 </p>	<p></p> <p>01-53940-02 10105-AA290</p>	<p></p> <p>02-53940-02</p> <p></p>	<p></p>	<p></p>	<p></p> <p>61-53940-00 2x 11044-AA483 93,7 Ø MLS</p> <p></p>	<p></p> <p>14-11006-01 11095-AA123 (8x) +11095-AA141 (4x)</p> <p></p>	<p></p> <p>71-53988-00 2x 13294-AA053</p> <p></p>	<p></p> <p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p> <p></p> <p>70-53989-00 ES 8x 13207-AA120</p> <p>70-53991-00 AS 8x 13211-AA110</p>	<p></p> <p>71-53992-00  2x 14035-AA383</p> <p></p> <p>71-52938-10  2x 44616-AA290</p> <p></p>	<p></p> <p>70-31414-10 </p>	<p></p> <p>81-53918-00  2x 80673-3030 33x49 A SL RD FPM</p> <p></p> <p>81-53333-00  2x 80678-6040 86x103 A SL LD MVQ</p> <p></p> <p>81-53239-00  2x 80673-2150 32x45 A SL RD ACM</p> <p></p> <p>81-53239-00  2x 80673-2150 32x45 A SL RD ACM</p> <p></p>
<p>Ltr.  EJ202</p> <p>90-101 kW (122-138 PS)</p> <p>FORESTER LEGACY OUTBACK</p> <p>08/97-10/05</p>	<p></p> <p>01-53940-02 10105-AA290</p>	<p></p> <p>02-53940-02</p> <p></p>			<p></p> <p>61-53940-00 2x 11044-AA483 93,7 Ø MLS</p> <p></p>	<p></p> <p>14-11006-01 11095-AA123 (8x) +11095-AA141 (4x)</p> <p></p>	<p></p> <p>71-53988-00 2x 13294-AA053</p> <p></p>	<p></p> <p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p> <p></p> <p>70-53991-00 8x 13211-AA110</p>	<p></p> <p>71-53992-00  2x 14035-AA383</p> <p></p> <p>71-52938-10  2x 44616-AA290</p> <p></p>		<p></p> <p>81-53918-00  2x 80673-3030 33x49 A SL RD FPM</p> <p></p> <p>81-53333-00  2x 80678-6040 86x103 A SL LD MVQ</p> <p></p> <p>81-53239-00  2x 80673-2150 32x45 A SL RD ACM</p> <p></p>

SUBARU












































































<p>Ltr.  EJ204</p> <p>108-118 kW (147-160 PS)</p> <p>LEGACY</p> <p>06/09-12/15 </p>					<p>61-11243-00 2x 11044-AA680 93,7 Ø 0,6 mm MLS</p> 	<p>14-11012-01 2x 11095-AA042 (6X)</p> 	<p>15-53998-01 R 13270-AA190 +13293-AA051 (2x)</p>  <p>15-53999-01 L 13272-AA140 +13293-AA051 (2x)</p> 	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>  <p>70-53989-00 ES 8x 13207-AA120</p>  <p>70-53991-00 AS 8x 13211-AA110</p> 	<p>71-17780-00  2x 14035-AA540</p>  <p>71-52938-10  2x 44616-AA290</p> 	<p>70-31414-10</p> 	<p>81-53918-00 K  2x 80673-3030 33x49 A SL RD FPM</p>  <p>81-53333-00 K  2x 80678-6040 86x103 A SL LD MVQ</p>  <p>81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM</p>  <p>81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM</p> 
<p>2,0 EJ204</p> <p>110 kW (150 PS)</p> <p>FORESTER</p> <p>01/08-09/13</p>	<p>01-11243-01 10105AA990</p>	<p>02-11243-01</p>			<p>61-11243-00 2x 11044-AA680 93,7 Ø 0,6 mm MLS</p> 	<p>14-11012-01 2x 11095-AA042 (6X)</p> 	<p>15-53998-01 R 13270-AA190 +13293-AA051 (2x)</p>  <p>15-53999-01 L 13272-AA140 +13293-AA051 (2x)</p> 	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>  <p>70-53989-00 ES 8x 13207-AA120</p>  <p>70-53991-00 AS 8x 13211-AA110</p> 	<p>71-53941-00  2x 14035-AA421  12/09</p>  <p>71-17780-00   2x 14035-AA540  01/10→</p>  <p>71-52938-10  2x 44616-AA290</p> 	<p>70-31414-10</p> 	<p>81-53918-00 K  2x 80673-3030 33x49 A SL RD FPM</p>  <p>81-53333-00 K  2x 80678-6040 86x103 A SL LD MVQ</p>  <p>81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM</p>  <p>81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM</p> 

SUBARU																
Ltr.																
2,0	EJ204	110 kW (150 PS)	LEGACY	09/07-12/09												
					01-11243-01 10105AA990	02-11243-01				61-11243-00 2x 11044-AA680 93,7 Ø 0,6 mm MLS 	14-11012-01 2x 11095-AA042 (6x) 	15-53998-01 R 2x 13270-AA190 +13293-AA051 (2x) 15-53999-01 L 13272-AA140 +13293-AA051 (2x) 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 70-53989-00 ES 8x 13207-AA120 70-53991-00 AS 8x 13211-AA110 	71-53941-00 K 2x 14035-AA421 71-52938-10 2x 44616-AA290 	70-31414-10 	81-53918-00 K 4x 80673-3030 33x49 A SL RD FPM 81-53333-00 K 4x 80678-6040 86x103 A SL LD MVQ 81-54006-00 N 4x 80674-2160 42x55 A SL RD FPM
2,0	EJ204	110-118 kW (150-160 PS)	FORESTER IMPREZA	06/05	01-11243-01 10105AA990	02-11243-01				61-11243-00 2x 11044-AA680 93,7 Ø 0,6 mm MLS 	14-11012-01 2x 11095-AA042 (6x) 	15-53998-01 R 2x 13270-AA190 +13293-AA051 (2x) 15-53999-01 L 13272-AA140 +13293-AA051 (2x) 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 70-53989-00 ES 8x 13207-AA120 70-53991-00 AS 8x 13211-AA110 	71-53941-00 K 2x 14035-AA421 71-52938-10 2x 44616-AA290 	70-31414-10 	81-53918-00 K 4x 80673-3030 33x49 A SL RD FPM 81-53333-00 K 4x 80678-6040 86x103 A SL LD MVQ 81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM 81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM

SUBARU

<p>Ltr.  EJ204</p> <p>116-118 kW (158-160 PS)</p> <p>FORESTER</p> <p>01/08-12/14</p> <p>1</p>	 <p>01-11243-01 10105AA990</p>	 <p>02-11243-01</p>			 <p>61-11243-00 2x 11044-AA680 93,7 Ø 0,6 mm MLS</p> 	 <p>14-11012-01 2x 11095-AA042 (6X)</p> 	 <p>15-53998-01 R 13270-AA190 +13293-AA051 (2x)</p>  <p>15-53999-01 L 13272-AA140 +13293-AA051 (2x)</p> 	 <p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>  <p>70-53989-00 ES 8x 13207-AA120</p> <p>70-53991-00 AS 8x 13211-AA110</p> 	 <p>71-17780-00  2x 14035-AA540</p>  <p>71-53941-00  2x 14035-AA421</p>  <p>71-52938-10  2x 44616-AA290</p> 	 <p>70-31414-10</p> 	 <p>81-53918-00 K  80673-3030 33x49 A SL RD FPM</p>  <p>81-53333-00 K  80678-6040 86x103 A SL LD MVQ</p>  <p>81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM</p>  <p>81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM</p> 
<p>2,0 EJ204</p> <p>118-121 kW (160-165 PS)</p> <p>LEGACY</p> <p>09/03-04/09</p>					 <p>61-10199-00 2x 11044-AA651 93,7 Ø MLS</p> 	 <p>14-11012-01 2x 11095-AA042 (6X)</p> 	 <p>15-53998-01 R 13270-AA190 +13293-AA051 (2x)</p>  <p>15-53999-01 L 13272-AA140 +13293-AA051 (2x)</p> 	 <p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>  <p>70-53989-00 ES 8x 13207-AA120</p> <p>70-53991-00 AS 8x 13211-AA110</p> 	 <p>71-17438-00  2x 16272-AA001</p>  <p>71-17461-00   2x 14035-AA492</p>  <p>71-54001-00  2x 14038-AA000</p> 	 <p>70-31414-10</p> 	 <p>81-53918-00 K  80673-3030 33x49 A SL RD FPM</p>  <p>81-53333-00 K  80678-6040 86x103 A SL LD MVQ</p>  <p>81-54006-00 N 4x 80674-2160 42x55 A SL RD FPM</p> 



























































SUBARU

<p>Ltr. </p>	<p>2,0 EJ205 125-160 kW (170-218 PS) FORESTER IMPREZA</p>	<p>06/98-04/01 </p>		<p>01-53940-01 10105-AA351</p> 	<p>01-53940-01 10105-AA351</p> 		<p>02-53940-01</p> 	<p>02-53940-01</p> 		<p>61-53940-00 2x 11044-AA483 93,7 Ø MLS</p> 	<p>61-53940-00 2x 11044-AA483 93,7 Ø MLS</p> 		<p>15-53946-01 R 13270-AA171 +13293-AA051 (2x)  01/99</p> 	<p>15-53947-01 R 13270-AA162 +13293-AA051 (2x)  02/99→</p> 		<p>12-53919-01 13207-AA050 (8x) +13211-AA050 (8x)</p>            	<p>15-53948-01 L 13272-AA094 +13293-AA051 (2x)</p> 		<p>71-53941-00  2x 14035-AA421</p> 	<p>71-53938-10  2x 44616-AA290</p> 		<p>70-31414-10</p> 	<p>70-31414-10</p> 		<p>81-53918-00  K 80673-3030 33x49 A SL RD FPM</p> 	<p>81-53918-00  K 80673-3030 33x49 A SL RD FPM</p> 		<p>81-53333-00  K 80678-6040 86x103 A SL LD MVQ</p> 	<p>81-53333-00  K 80678-6040 86x103 A SL LD MVQ</p> 		<p>81-53944-00 N 4x 80673-2160 32x55 A SL RD FPM</p> 	<p>81-53944-00 N 4x 80673-2160 32x55 A SL RD FPM</p> 
<p>2,0 EJ205 130-169 kW (177-230 PS) FORESTER IMPREZA IMPREZA WRX</p>	<p>12/00-03/07</p>	<p>01-53940-01 10105-AA351</p> 	<p>02-53940-01</p> 	<p>61-53940-00 2x 11044-AA483 93,7 Ø MLS</p> 	<p>15-53947-01 R 13270-AA162 +13293-AA051 (2x)</p> 	<p>12-53919-01 13207-AA050 (8x) +13211-AA050 (8x)</p>           	<p>15-53948-01 L 13272-AA094 +13293-AA051 (2x)</p> 	<p>71-53941-00  2x 14035-AA421</p> 	<p>71-52938-10  2x 44616-AA290</p> 	<p>81-53918-00  K 80673-3030 33x49 A SL RD FPM</p> 	<p>81-53333-00  K 80678-6040 86x103 A SL LD MVQ</p> 																					

SUBARU

Ltr.	Code	Power	Model	Date	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11		
2,0	EJ205	150-184 kW (204-250 PS)	IMPREZA	12/01-03/07	01-53940-01 10105-AA351 	02-53940-01 			61-53940-00 2x 11044-AA483 93,7 Ø MLS 		15-53947-01 R 13270-AA162 +13293-AA051 (2x) 	12-53919-01 13207-AA050 (8x) +13211-AA050 (8x) 	71-53941-00 2x 14035-AA421 	70-31414-10 	81-53918-00 K 80673-3030 33x49 A SL RD FPM 		
											15-53948-01 13272-AA094 +13293-AA051 (2x) 		71-52938-10 2x 44616-AA290 	71-53942-00 16 	71-53943-00 16 	81-53333-00 K 80678-6040 86x103 A SL LD MVQ 	
															81-53944-00 N 4x 80673-2160 32x55 A SL RD FPM 		
2,0	EJ207	195-224 kW (265-305 PS)	IMPREZA	04/01-07/05	01-53940-01 10105-AA351 10/02→ 	02-53940-01 10/02→ 			61-53940-00 2x 11044-AA483 93,7 Ø MLS 	14-11012-01 2x 11095-AA042 (6x) 	15-20113-01 R 13270-AA152 +13293-AA051 (2x) 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 	71-53941-00 2x 14035-AA421 	70-31414-10 	81-53918-00 K 80673-3030 33x49 A SL RD FPM 		
											15-20119-01 R 13272-AA075 +13293-AA051 (2x) 		71-54002-00 2x 14075-AA161 	71-54001-00 2x 14038-AA000 	70-53989-00 ES 8x 13207-AA120 	70-53991-00 AS 8x 13211-AA110 	81-53333-00 K 80678-6040 86x103 A SL LD MVQ
															81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM 		
															81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM 		































SUBARU

<p>Ltr.  2,0 EJ207 235 kW (320 PS) IMPREZA  02/04-07/05 </p>					 <p>61-53940-00 2x 11044-AA483 93,7 Ø MLS</p> 	 <p>14-11012-01 2x 11095-AA042 (6x)</p> 	 <p>15-20113-01  R 13270-AA152 +13293-AA051 (2x)</p>  <p>15-20119-01  L 13272-AA075 +13293-AA051 (2x)</p> 	 <p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>  <p>70-53989-00 ES 8x 13207-AA120</p> <p>70-53991-00 AS 8x 13211-AA110</p> 	 <p>71-53941-00  2x 14035-AA421</p>  <p>71-54002-00  2x 14075-AA161</p>  <p>71-54001-00 2x 14038-AA000</p> 	 <p>70-31414-10</p> 	 <p>81-53918-00  K 80673-3030 33x49 A SL RD FPM</p>  <p>81-53333-00  K 80678-6040 86x103 A SL LD MVQ</p>  <p>81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM</p>  <p>81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM</p> 
<p>2,0 EJ208 206 kW (280 PS) LEGACY 06/02-12/14</p>	<p>01-53940-01 10105-AA351</p> 	<p>02-53940-01</p> 			 <p>61-53940-00 2x 11044-AA483 93,7 Ø MLS</p> 	 <p>14-11012-01 2x 11095-AA042 (6x)</p> 	 <p>15-53947-01 R 13270-AA162 +13293-AA051 (2x)</p>  <p>15-53948-01 L 13272-AA094 +13293-AA051 (2x)</p> 	 <p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>  <p>70-53989-00 ES 8x 13207-AA120</p> <p>70-53991-00 AS 8x 13211-AA110</p> 	 <p>71-53941-00  2x 14035-AA421</p>  <p>71-54001-00 2x 14038-AA000</p> 	 <p>70-31414-10</p> 	 <p>81-53918-00  K 80673-3030 33x49 A SL RD FPM</p>  <p>81-53333-00  K 80678-6040 86x103 A SL LD MVQ</p>  <p>81-53944-00 N 4x 80673-2160 32x55 A SL RD FPM</p> 





















































SUBARU

Ltr.  2,0 FA20 FA20E FA20F 177-206 kW (240-280 PS) 03/13 











































 FORESTER FORESTER XT IMPREZA LEGACY D OUTBACK D WRX

										
<p>01-10266-01 10105-AB560</p>	<p>02-10266-01</p>			<p>61-10266-00 L 10944-AA110 89,5 Ø 0,5 mm MLS</p>  <p>61-10267-00 R 11044-AA821 89,5 Ø 0,5 mm MLS</p> 	<p>14-11012-01 11095-AA042 (6X) 2x</p> 	<p>15-10675-01 R 13270-AA250 +10966-AA040 (2X)</p>  <p>15-10675-01 L 13272-AA180 +10966-AA040 (2X)</p>  <p>71-10675-00 R 13270-AA250</p>  <p>71-10676-00 L 13272-AA180</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p>  <p>70-10695-00 AS 13211-AA100 8x</p>  <p>70-11562-00 ES 13207-AA110 8x</p> 	<p>11-12989-01  14035-AA620 (4x)</p>  <p>71-12997-00  2x 14038-AA050</p> 	<p>70-31414-10 </p>	<p>81-53387-00 K  80675-0070 50x62 RD</p>  <p>81-10384-00 K  80679-2010 92x109 A SL LD FPM</p> 

SUBARU

<p>Ltr. </p> <p>2,0 FA20D 147-153 kW (200-208 PS) BRZ 06/12</p>	 <p>01-10080-01 10105-AB550</p>	 <p>02-10080-01</p> 			 <p>61-10080-00 L 10944-AA100 89,5 Ø 0,5 mm MLS</p>  <p>61-10081-00 R 11044-AA810 89,5 Ø 0,5 mm MLS</p> 	 <p>14-11012-01 11095-AA042 (6X)</p> 	<p>2x 15-10675-01 R 13270-AA250 +10966-AA040 (2X)</p>  <p>15-10676-01 L 13272-AA180 +10966-AA040 (2X)</p>  <p>71-10675-00 R 13270-AA250</p>  <p>71-10676-00 L 13272-AA180</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p>  <p>15-10675-00 R 13270-AA250</p>  <p>71-10695-00 AS 13211-AA100</p>  <p>71-11562-00 ES 13207-AA110</p> 	<p>71-10677-00 L  2x 14035-AA610</p>  <p>71-52938-10  2x 44616-AA290</p> 	<p>70-31414-10</p> 	<p>81-53387-00 K  80675-0070 50x62 RD</p>  <p>81-10384-00 K  80679-2010 92x109 A SL LD FPM</p> 
<p>2,0 FB20 FB20B 110 kW (150 PS) FORESTER IMPREZA LEGACY LEVORG 01/10</p>	 <p>01-10086-01 10105-AB730</p>	 <p>02-10086-01</p> 			 <p>61-10086-00 L 10944-AA070 85,5 Ø 0,5 mm MLS</p>  <p>61-10087-00 R 11044-AA780 85,5 Ø 0,5 mm MLS</p> 	 <p>14-11012-01 11095-AA042 (6X)</p> 	<p>2x 71-10693-00 R 13270-AA240</p>  <p>71-10694-00 L 13272-AA170</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p>  <p>71-10695-00 AS 13211-AA100</p>  <p>71-11562-00 ES 13207-AA110</p> 	<p>71-10697-00 L  2x 14035-AA580</p>  <p>71-52938-10  2x 44616-AA290</p> 	<p>70-31414-10</p> 	<p>81-53387-00 K  80675-0070 50x62 RD</p>  <p>81-10384-00 K  80679-2010 92x109 A SL LD FPM</p> 

SUBARU

<p>Ltr. </p>	<p>2,0 FB20A 110 kW (150 PS) LEVORG 01/19</p>											
<p>2,0 FB20A 110 kW (150 PS) LEVORG 01/19</p>	<p>01-10086-01 10105-AB730</p>	<p>02-10086-01</p> 			<p>61-10086-00 L 10944-AA070 85,5 Ø 0,5 mm MLS</p>  <p>61-10087-00 R 11044-AA780 85,5 Ø 0,5 mm MLS</p> 	<p>14-11012-01 11095-AA042 (6x)</p> 	<p>2x 71-10693-00 R 13270-AA240</p>  <p>71-10694-00 L 13272-AA170</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p>  <p>70-10695-00 AS 13211-AA100 8x</p>  <p>70-11562-00 ES 13207-AA110 8x</p> 	<p>71-10697-00 L 14035-AA580 2x</p>  <p>71-16042-00 L 14035-AA570 2x</p>  <p>71-52938-10 44616-AA290 2x</p> 	<p>70-31414-10</p> 	<p>81-53387-00 K 80675-0070 50x62 RD</p>  <p>81-10384-00 K 80679-2010 92x109 A SL LD FPM</p> 	
<p>2,0 FB20B 110 kW (150 PS) FORESTER IMPREZA XV 07/11</p>	<p>01-10086-01 10105-AB730</p>	<p>02-10086-01</p> 			<p>61-10086-00 L 10944-AA070 85,5 Ø 0,5 mm MLS</p>  <p>61-10087-00 R 11044-AA780 85,5 Ø 0,5 mm MLS</p> 	<p>14-11012-01 11095-AA042 (6x)</p> 	<p>2x 71-10693-00 R 13270-AA240</p>  <p>71-10694-00 L 13272-AA170</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p>  <p>70-10695-00 AS 13211-AA100 8x</p>  <p>70-11562-00 ES 13207-AA110 8x</p> 	<p>71-16042-00 L 14035-AA570 2x</p>  <p>71-10697-00 L 14035-AA580 2x</p>  <p>71-52938-10 44616-AA290 2x</p> 	<p>70-31414-10</p> 	<p>81-53387-00 K 80675-0070 50x62 RD</p>  <p>81-10384-00 K 80679-2010 92x109 A SL LD FPM</p> 	

SUBARU


Ltr.  2,0 FB20C FB20D 110-115 kW (150-156 PS) FORESTER IMPREZA XV  10/16



01-11327-01
10105-AB740



02-11327-01



61-11327-00 R
11044-AA870
87 Ø
0,5 mm
MLS




61-11328-00 L
10944-AA160
87 Ø
0,5 mm
MLS




14-11012-01
11095-AA042 (6x)




15-20014-01 R
13270-AA300
+10966-AA041 (2x)
+13293-AA060




15-20017-01 L
13272-AA250
+10966-AA041 (2x)
+13293-AA060




71-20014-00 R
13270-AA300



71-20017-00 L
13272-AA250




12-10695-01
13207-AA110 (8x)
+13211-AA100 (8x)



70-10695-00 AS 8x
13211-AA100



70-11562-00 ES 8x
13207-AA110



71-20018-00 L 4x
14035-AA690



71-52938-10 2x
44616-AA290



70-31414-10



81-53387-00 K 80675-0070 50x62 RD



81-10384-00 K 80679-2010 92x109 A SL LD FPM



SUBARU




























Ltr. 

2,0 FB20W








107-110 KW (145-150 PS)

1


										
<p>01-11327-01 10105-AB740</p>	<p>02-11327-01</p> 			<p>61-11327-00 R 11044-AA870 87 Ø 0,5 mm MLS</p>  <p>61-11328-00 L 10944-AA160 87 Ø 0,5 mm MLS</p> 	<p>14-11012-01 11095-AA042 (6x) 2x</p> 	<p>15-20014-01 R 13270-AA300 +10966-AA041 (2x) +13293-AA060</p>  <p>15-20017-01 L 13272-AA250 +10966-AA041 (2x) +13293-AA060</p>  <p>71-20014-00 R 13270-AA300</p>  <p>71-20017-00 L 13272-AA250</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p>  <p>70-10695-00 AS 8x 13211-AA100</p>  <p>70-11562-00 ES 8x 13207-AA110</p> 	<p>71-20036-00 L 4x 14035-AA770</p>  <p>71-52938-10 2x 44616-AA290</p> 	<p>70-31414-10</p> 	<p>81-53387-00 K → 80675-0070 50x62 RD</p>  <p>81-10384-00 K → 80679-2010 92x109 A SL LD FPM</p> 

SUBARU

Ltr.  2,0 FB20X 107-110 kW (145-150 PS) FORESTER Hybrid  04/18 



01-11327-01
10105-AB740



61-11327-00 R
11044-AA870
87 Ø
0,5 mm
MLS




61-11328-00 L
10944-AA160
87 Ø
0,5 mm
MLS




14-11012-01
11095-AA042 (6x)




15-20014-01 R
13270-AA300
+10966-AA041 (2x)
+13293-AA060




15-20017-01 L
13272-AA250
+10966-AA041 (2x)
+13293-AA060




71-20014-00 R
13270-AA300



71-20017-00 L
13272-AA250



12-10695-01
13207-AA110 (8x)
+13211-AA100 (8x)



70-10695-00 AS 8x
13211-AA100



70-11562-00 ES 8x
13207-AA110



71-52938-10 2x
44616-AA290



70-31414-10


81-53387-00 K↔
80675-0070
50x62
RD



81-10384-00 K↔
80679-2010
92x109
A SL LD FPM



2,2 EJ22 EMPI 94-100 kW (128-136 PS) LEGACY 01/89-03/99

01-53000-01
10105-AA021




02-53000-01



61-53000-00 2x
11044-AA114
98 Ø




71-52951-00 2x
13294-AA010



12-52829-01
14035-AA290




71-52942-00 L↔ 2x
14035-AA290



71-52938-10 2x
44616-AA290



71-52946-00



81-53333-00 K↔
80678-6040
86x103
A SL LD MVQ



81-53239-00 N↔
80673-2150
32x45
A SL RD ACM


















































SUBARU														
Ltr.														
2,5	EJ25	115 kW (156 PS)	FORESTER LEGACY OUTBACK	10/98-12/08	01-53905-01 10105-AA860 	02-53905-01 			61-53920-00 2x 11044-AA642 101.3 0 MLS 	14-11006-03 2x 11095-AA123 (4x) +11095-AA141 (2x) 	15-53988-01 2x 13294-AA053 +10966-AA030 (2x) 71-53988-00 2x 13294-AA053 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 70-53989-00 ES 8x 13207-AA120 70-53991-00 AS 8x 13211-AA110 	71-53992-00 2x 14035-AA383 71-52938-10 2x 44616-AA290 70-31414-10 	81-53918-00 K 80673-3030 33x49 A SL RD FPM 81-53333-00 K 80678-6040 86x103 A SL LD MVQ 81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM
2,5	EJ25	121-127 kW (165-173 PS)	LEGACY	09/03-12/09	01-53905-03 10105-AB100 				61-53920-00 2x 11044-AA642 101.3 0 MLS 	14-11006-03 2x 11095-AA123 (4x) +11095-AA141 (2x) 	15-53988-01 2x 13294-AA053 +10966-AA030 (2x) 71-53988-00 2x 13294-AA053 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 70-53989-00 ES 8x 13207-AA120 70-53991-00 AS 8x 13211-AA110 	71-53992-00 2x 14035-AA383 71-53997-00 2x 14075-AA210 71-52938-10 2x 44616-AA290 70-31414-10 	81-53918-00 K 80673-3030 33x49 A SL RD FPM 81-53333-00 K 80678-6040 86x103 A SL LD MVQ 81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM

SUBARU

Ltr.	Engine	Power	Model	Year	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11
2,5	EJ25	125 kW (170 PS)	LEGACY OUTBACK	05/09	<p>01-53910-05 10105-AB270</p>	<p>02-53910-05</p>			<p>61-53910-00 2x 11044-AA770 101.3 Ø MLS</p>		<p>71-53996-00 2x 13294-AA070</p>	<p>12-53989-01 2x 13207-AA120 (8x) +13211-AA110 (8x)</p>	<p>71-17780-00 2x 14035-AA540</p>	<p>70-31414-10</p>	<p>81-53918-00 K↔ 80673-3030 33x49 A SL RD FPM</p> <p>81-53333-00 K↔ 80678-6040 86x103 A SL LD MVQ</p> <p>81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM</p>
2,5	EJ25	126 kW (171 PS)	FORESTER	01/09-09/13	<p>01-53905-02 10105-AB150</p>	<p>02-53905-02</p>			<p>61-53920-00 2x 11044-AA642 101.3 Ø MLS</p>		<p>71-53996-00 2x 13294-AA070</p>	<p>12-53989-01 2x 13207-AA120 (8x) +13211-AA110 (8x)</p>	<p>71-53992-00 2x 14035-AA383</p>	<p>70-31414-10</p>	<p>81-53918-00 K↔ 80673-3030 33x49 A SL RD FPM</p> <p>81-53333-00 K↔ 80678-6040 86x103 A SL LD MVQ</p> <p>81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM</p>

SUBARU

Ltr.	Engine	Power	Model	Year	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11
2,5	EJ25	127 kW (173 PS)	LEGACY	01/08-12/09	01-53905-02 10105-AB150 	02-53905-02 			61-53920-00 2x 11044-AA642 101.3 Ø MLS 	14-11006-03 2x 11095-AA123 (4x) +11095-AA141 (2x) 	71-53996-00 2x 13294-AA070 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 	71-53992-00  2x 14035-AA383 	70-31414-10 	81-53918-00  80673-3030 33x49 A SL RD FPM 
												71-53997-00  2x 14075-AA210 	71-52938-10 2x 44616-AA290 		81-53333-00  80678-6040 86x103 A SL LD MVQ 
												71-53991-00  8x 13211-AA110 		81-53239-00  2x 80673-2150 32x45 A SL RD ACM 	
2,5	EJ25	155 kW (211 PS)	FORESTER	12/03-05/05	01-53920-01 10105-AA600 	02-53920-01 			61-53920-00 2x 11044-AA642 101.3 Ø MLS 	14-11012-01 2x 11095-AA042 (6x) 	15-53998-01  R 13270-AA190 +13293-AA051 (2x) 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 	71-53941-00  2x 14035-AA421 	70-31414-10 	81-53918-00  80673-3030 33x49 A SL RD FPM 
												15-53999-01  L 13272-AA140 +13293-AA051 (2x) 	71-54002-00   2x 14075-AA161 		81-53333-00  80678-6040 86x103 A SL LD MVQ 
												70-53989-00  ES 8x 13207-AA120 	71-53991-00  AS 8x 13211-AA110 	81-53944-00  N 80673-2160 32x55 A SL RD FPM 	
															81-54006-00  N 80674-2160 42x55 A SL RD FPM 

SUBARU																
2,5	EJ25D	110-123 kW (150-167 PS)	FORESTER LEGACY LEGACY OUTBACK	01/96-05/08	01-53915-01 10105-AA401 	02-53915-01 			61-53915-00 2x 11044-AA610 101 Ø MLS 		15-53933-01 R 13270-AA111 +13293-AA051 (2x) 	12-53919-01 13207-AA050 (8x) +13211-AA050 (8x) 	71-53921-00 2x 14035-AA281 	70-31414-10 	81-53918-00 K 80673-3030 33x49 A SL RD FPM 	
											15-53937-01 L 13272-AA111 +13293-AA051 (2x) 		71-52938-10 2x 44616-AA290 		81-53333-00 K 80678-6040 86x103 A SL LD MVQ 	
2,5	EJ251	112-130 kW (152-177 PS)	FORESTER IMPREZA OUTBACK	03/01-06/10	01-53905-01 10105-AA860 	02-53905-01 			61-53920-00 2x 11044-AA642 101,3 Ø MLS 		71-53988-00 2x 13294-AA053 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 	71-53992-00 2x 14035-AA383 	70-31414-10 	81-53918-00 K 80673-3030 33x49 A SL RD FPM 	
												70-53989-00 ES 8x 13207-AA120 		71-52938-10 2x 44616-AA290 		81-53333-00 K 80678-6040 86x103 A SL LD MVQ
												70-53991-00 AS 8x 13211-AA110 				81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM

SUBARU



SUBARU																	
Ltr.																	
2,5	EJ253	123 kW (167 PS)	LEGACY OUTBACK	09/09	<p>01-53910-05 10105-AB270</p>	<p>02-53910-05</p>			<p>61-53910-00 2x 11044-AA770 101.3 Ø MLS</p>	<p>14-11006-03 2x 11095-AA123 (4x) +11095-AA141 (2x) 12/09</p>	<p>71-53996-00 2x 13294-AA070</p>	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>	<p>71-17780-00 2x 14035-AA540</p>	<p>70-31414-10</p>	<p>81-53918-00 K 80673-3030 33x49 A SL RD FPM</p>	<p>81-53333-00 K 80678-6040 86x103 A SL LD MVQ</p>	<p>81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM</p>
2,5	EJ253	123-129 kW (167-175 PS)	LEGACY OUTBACK	01/10-12/14	<p>01-53910-05 10105-AB270</p>	<p>02-53910-05</p>			<p>61-53910-00 2x 11044-AA770 101.3 Ø MLS</p>	<p>14-11006-03 2x 11095-AA123 (4x) +11095-AA141 (2x)</p>	<p>71-53996-00 2x 13294-AA070</p>	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>	<p>71-17780-00 2x 14035-AA540</p>	<p>70-31414-10</p>	<p>81-53918-00 K 80673-3030 33x49 A SL RD FPM</p>	<p>81-53333-00 K 80678-6040 86x103 A SL LD MVQ</p>	<p>81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM</p>





















SUBARU															
2,5	EJ253	129 kW (175 PS)	FORESTER	01/05-10/12	01-53905-03 10105-AB100 	02-53905-03 			61-53920-00 2x 11044-AA642 101.3 Ø MLS 	14-11006-03 2x 11095-AA123 (4x) +11095-AA141 (2x) 	15-53988-01 2x 13294-AA053 +10966-AA030 (2x) 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 	71-53982-00 2x 14035-AA383 	70-31414-10 	81-53918-00 K → 80673-3030 33x49 A SL RD FPM
												71-52938-10 2x 44616-AA290 		81-53333-00 K → 80678-6040 86x103 A SL LD MVQ 	
												70-53989-00 ES 8x 13207-AA120 		81-53239-00 N 2x 80673-2150 32x45 A SL RD ACM 	
												70-53991-00 AS 8x 13211-AA110 			
2,5	EJ255	169-195 kW (230-265 PS)	FORESTER FORESTER Turbo IMPREZA	01/08					61-53910-00 2x 11044-AA770 101.3 Ø MLS 	14-11012-01 2x 11095-AA042 (6x) 	15-53998-01 R 13270-AA190 +13293-AA051 (2x) 	12-53989-01 13207-AA120 (8x) +13211-AA110 (8x) 	71-53941-00 L → 2x 14035-AA421 	70-31414-10 	81-53918-00 K → 80673-3030 33x49 A SL RD FPM
												15-53999-01 L 13272-AA140 +13293-AA051 (2x) 		81-53333-00 K → 80678-6040 86x103 A SL LD MVQ 	
												70-53989-00 ES 8x 13207-AA120 		81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM 	
												70-53991-00 AS 8x 13211-AA110 		81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM 	

SUBARU





















Ltr.	Engine	Power	Model	Year	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11	
2,5	EJ255	169-200 kW (230-272 PS)	FORESTER IMPREZA	05/05-12/08	<p>01-53910-01 10105-AB010</p>	<p>02-53910-01</p>				<p>61-53910-00 2x 11044-AA770 101.3 Ø MLS</p>	<p>14-11012-01 2x 11095-AA042 (6X)</p>	<p>15-53998-01 R 13270-AA190 +13293-AA051 (2x)</p> <p>15-53999-01 L 13272-AA140 +13293-AA051 (2x)</p>	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p> <p>70-53989-00 ES 8x 13207-AA120</p> <p>70-53991-00 AS 8x 13211-AA110</p>	<p>71-53941-00 L 2x 14035-AA421</p> <p>71-54002-00 L 2x 14075-AA161</p> <p>71-54001-00 2x 14038-AA000</p>	<p>70-31414-10</p>	<p>81-53918-00 K 2x 80673-3030 33x49 A SL RD FPM</p> <p>81-53333-00 K 2x 80678-6040 86x103 A SL LD MVQ</p> <p>81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM</p> <p>81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM</p>
2,5	EJ255	188 kW (255 PS)	IMPREZA WRX	02/09-12/10						<p>61-53910-00 2x 11044-AA770 101.3 Ø MLS</p>	<p>14-11012-01 2x 11095-AA042 (6X)</p>	<p>15-53998-01 R 13270-AA190 +13293-AA051 (2x)</p> <p>15-53999-01 L 13272-AA140 +13293-AA051 (2x)</p>	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p> <p>70-53989-00 ES 8x 13207-AA120</p> <p>70-53991-00 AS 8x 13211-AA110</p>	<p>71-53941-00 L 2x 14035-AA421</p> <p>71-54002-00 L 2x 14075-AA161</p> <p>71-54001-00 2x 14038-AA000</p>	<p>70-31414-10</p>	<p>81-53918-00 K 2x 80673-3030 33x49 A SL RD FPM</p> <p>81-53333-00 K 2x 80678-6040 86x103 A SL LD MVQ</p> <p>81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM</p> <p>81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM</p>

SUBARU
















































Ltr.  2,5 EJ255 195 kW (265 PS) IMPREZA WRX  01/09-12/14

										
61-53910-00 2x 11044-AA770 101.3 0 MLS	14-11012-01 2x 11095-AA042 (6x)	15-53998-01 R 2x 13270-AA190 +13293-AA051 (2x)	12-53989-01 2x 13207-AA120 (8x) +13211-AA110 (8x)	71-53941-00 K 2x 14035-AA421	70-31414-10 2x	81-53918-00 K 4x 80673-3030 33x49 A SL RD FPM				
		 15-53999-01 L 13272-AA140 +13293-AA051 (2x)	 70-53989-00 ES 8x 13207-AA120 70-53991-00 AS 8x 13211-AA110	 71-54002-00 L 2x 14075-AA161 71-54001-00 2x 14038-AA000		 81-53333-00 K 4x 80678-6040 86x103 A SL LD MVQ  81-54006-00 N 4x 80674-2160 42x55 A SL RD FPM 				
























































2,5 EJ255 195 kW (265 PS) LEGACY 07/10-12/14

										
61-53910-00 2x 11044-AA770 101.3 0 MLS	14-11012-01 2x 11095-AA042 (6x)	15-53999-01 L 2x 13272-AA140 +13293-AA051 (2x)	12-53989-01 2x 13207-AA120 (8x) +13211-AA110 (8x)	71-53941-00 K 2x 14035-AA421	70-31414-10 2x	81-53918-00 K 4x 80673-3030 33x49 A SL RD FPM				
		 15-53999-01 L 13272-AA140 +13293-AA051 (2x)	 70-53989-00 ES 8x 13207-AA120 70-53991-00 AS 8x 13211-AA110	 71-17461-00 L 4x 14035-AA492 71-54001-00 2x 14038-AA000		 81-53333-00 K 4x 80678-6040 86x103 A SL LD MVQ  81-54006-00 N 4x 80674-2160 42x55 A SL RD FPM 				

SUBARU

<p>Ltr. </p>											
<p>2,5 EJ257 195-221 kW (265-300 PS) IMPREZA 09/05-12/07</p>	<p>01-53910-01 10105-AB010 1 ⇒ 06/06</p>  <p>01-53910-02 10105-AB080 1 ⇒ 07/06 →</p> 	<p>02-53910-01 1 ⇒ 06/06</p>  <p>02-53910-02 1 ⇒ 07/06 →</p> 			<p>61-53910-00 2x 11044-AA770 101.3 Ø MLS</p> 	<p>14-11012-01 2x 11095-AA042 (6x)</p> 	<p>15-53998-01 R 13270-AA190 +13293-AA051 (2x)</p>  <p>15-53999-01 L 13272-AA140 +13293-AA051 (2x)</p> 	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>  <p>70-53989-00 ES 8x 13207-AA120</p>  <p>70-53991-00 AS 8x 13211-AA110</p> 	<p>71-53941-00 L 2x 14035-AA421</p>  <p>71-54002-00 L 2x 14075-AA161</p>  <p>71-54001-00 2x 14038-AA000</p> 	<p>70-31414-10</p> 	<p>81-53918-00 K ← 80673-3030 33x49 A SL RD FPM</p>  <p>81-53333-00 K → 80678-6040 86x103 A SL LD MVQ</p>  <p>81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM</p>  <p>81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM</p> 
<p>2,5 EJ257 199-294 kW (270-400 PS) IMPREZA IMPREZA WRX WRX 01/08</p>	<p>01-53910-03 10105-AB200</p> 	<p>02-53910-03</p> 			<p>61-53910-00 2x 11044-AA770 101.3 Ø MLS</p> 	<p>14-11012-01 2x 11095-AA042 (6x)</p> 	<p>15-53998-01 R 13270-AA190 +13293-AA051 (2x)</p>  <p>15-53999-01 L 13272-AA140 +13293-AA051 (2x)</p> 	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>  <p>70-53989-00 ES 8x 13207-AA120</p>  <p>70-53991-00 AS 8x 13211-AA110</p> 	<p>71-53941-00 L 2x 14035-AA421</p>  <p>71-54002-00 L 2x 14075-AA161</p>  <p>71-54001-00 2x 14038-AA000</p> 	<p>70-31414-10</p> 	<p>81-53918-00 K ← 80673-3030 33x49 A SL RD FPM</p>  <p>81-53333-00 K → 80678-6040 86x103 A SL LD MVQ</p>  <p>81-54006-00 N 4x 80674-2160 42x55 A SL RD FPM</p> 

































SUBARU

<p>Ltr. </p>											
<p>2,5 EJ257 235-243 kW (320-330 PS) IMPREZA IMPREZA WRX 02/07-12/10 </p>	<p>01-53910-02 10105-AB080</p> 	<p>02-53910-02</p> 			<p>61-53910-00 2x 11044-AA770 101,3 Ø MLS</p> 	<p>14-11012-01 2x 11095-AA042 (6x)</p> 	<p>15-53998-01 R 13270-AA190 +13293-AA051 (2x)</p>  <p>15-53999-01 L 13272-AA140 +13293-AA051 (2x)</p> 	<p>12-53989-01 13207-AA120 (8x) +13211-AA110 (8x)</p>  <p>70-53989-00 ES 8x 13207-AA120</p>  <p>70-53991-00 AS 8x 13211-AA110</p> 	<p>71-53941-00 L 2x 14035-AA421</p>  <p>71-54002-00 L 2x 14075-AA161</p>  <p>71-54001-00 2x 14038-AA000</p> 	<p>70-31414-10</p> 	<p>81-53918-00 K  80673-3030 33x49 A SL RD FPM</p>  <p>81-53333-00 K  80678-8040 86x103 A SL LD MVQ</p>  <p>81-53944-00 N 2x 80673-2160 32x55 A SL RD FPM</p>  <p>81-54006-00 N 2x 80674-2160 42x55 A SL RD FPM</p> 
<p>2,5 FB25 126 kW (171 PS) FORESTER 11/12</p>	<p>01-10259-01 10105-AB580</p> 	<p>02-10259-01</p> 			<p>61-10259-00 L 10944-AA080 95,6 Ø 0,5 mm MLS</p>  <p>61-10260-00 R 11044-AA790 95,6 Ø 0,5 mm MLS</p> 	<p>14-11012-01 2x 11095-AA042 (6x)</p> 	<p>71-10693-00 R 13270-AA240</p>  <p>71-10694-00 L 13272-AA170</p> 	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p>  <p>70-10695-00 AS 8x 13211-AA100</p>  <p>70-11562-00 ES 8x 13207-AA110</p> 	<p>71-10697-00 L 2x 14035-AA580</p>  <p>71-16042-00   14035-AA570</p>  <p>71-12997-00   2x 14038-AA050</p>  <p>71-52938-10 2x 44616-AA290</p> 	<p>70-31414-10</p> 	<p>81-53387-00 K  80675-0070 50x62 RD</p>  <p>81-10384-00 K  80679-2010 92x109 A SL LD FPM</p> 

SUBARU

Ltr.	Motor	Power (kW/PS)	Model	Date	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11			
2,5	FB25	126-127 kW (171-173 PS)	FORESTER	03/11	<p>01-10259-01 10105-AB580</p>	<p>02-10259-01</p>			<p>61-10259-00 L 10944-AA080 95,6 Ø 0,5 mm MLS</p> <p>61-10260-00 R 11044-AA790 95,6 Ø 0,5 mm MLS</p>	<p>14-11012-01 11095-AA042 (6x)</p>	2x	<p>71-10693-00 R 13270-AA240</p> <p>71-10694-00 L 13272-AA170</p>	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p> <p>70-10695-00 AS 13211-AA100</p> <p>70-11562-00 ES 13207-AA110</p>	8x	<p>71-10697-00 L </p> <p>14035-AA580</p> <p>71-16042-00 X </p> <p>14035-AA570</p> <p>71-52938-10 </p> <p>44616-AA290</p>	2x	<p>70-31414-10</p>	<p>81-53387-00 K </p> <p>80675-0070 50x62 RD</p> <p>81-10384-00 K </p> <p>80679-2010 92x109 A SL LD FPM</p>
2,5	FB25	127 kW (173 PS)	LEGACY	07/12-12/14	<p>01-10259-01 10105-AB580</p> <p>01-10259-02 10105-AB700</p>	<p>02-10259-01</p> <p>02-10259-02</p>			<p>61-10259-00 L 10944-AA080 95,6 Ø 0,5 mm MLS</p> <p>61-10260-00 R 11044-AA790 95,6 Ø 0,5 mm MLS</p>	<p>14-11012-01 11095-AA042 (6x)</p>	2x	<p>71-10693-00 R 2x 13270-AA240</p> <p>71-10693-00 R 13270-AA240</p> <p>71-10694-00 L 2x 13272-AA170</p> <p>71-10694-00 L 13272-AA170</p>	<p>12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)</p> <p>70-10695-00 AS 13211-AA100</p> <p>70-11562-00 ES 13207-AA110</p>	8x	<p>71-10697-00 L </p> <p>14035-AA580</p> <p>71-18107-00 L </p> <p>14035-AA680</p> <p>71-52938-10 </p> <p>44616-AA290</p>	2x	<p>70-31414-10</p>	<p>81-53387-00 K </p> <p>80675-0070 50x62 RD</p> <p>81-10384-00 K </p> <p>80679-2010 92x109 A SL LD FPM</p>

SUBARU

Ltr.	Engine	Power	Model	Year	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11		
2,5	FB25 FB25C FB25D	129-136 kW (175-185 PS)	FORESTER LEGACY OUTBACK	07/14	01-10259-02 10944-AA080 10105-AB700 	02-10259-02 			61-10259-00 L 10944-AA080 95,6 Ø 0,5 mm MLS  61-10260-00 R 11044-AA790 95,6 Ø 0,5 mm MLS 	14-11012-01 11095-AA042 (6x) 	2x	71-10693-00 R 13270-AA240  71-10694-00 L 13272-AA170 	12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)  70-10695-00 AS 13211-AA100 8x  70-11562-00 ES 13207-AA110 8x 	71-18107-00 L → 14035-AA680  71-52938-10 → 44616-AA290 2x  	2x	70-31414-10 	81-53387-00 K → 80675-0070 50x62 RD  81-10384-00 K → 80679-2010 92x109 A SL LD FPM 
2,5	FB25A FB25B	127 kW (173 PS)	LEGACY OUTBACK	07/12	01-10259-01 10105-AB580 	02-10259-01 			61-10259-00 L 10944-AA080 95,6 Ø 0,5 mm MLS  61-10260-00 R 11044-AA790 95,6 Ø 0,5 mm MLS 	14-11012-01 11095-AA042 (6x) 	2x	71-10693-00 R 13270-AA240  71-10694-00 L 13272-AA170 	12-10695-01 13207-AA110 (8x) +13211-AA100 (8x)  70-10695-00 AS 13211-AA100 8x  70-11562-00 ES 13207-AA110 8x 	71-10697-00 L → 14035-AA580  71-52938-10 → 44616-AA290 2x  	2x	70-31414-10 	81-53387-00 K → 80675-0070 50x62 RD  81-10384-00 K → 80679-2010 92x109 A SL LD FPM 

SUBARU

Ltr.	Engine	Power	Model	Date	Part 1	Part 2	Part 3	Part 4	Part 5	Part 6	Part 7	Part 8	Part 9	Part 10	Part 11			
3,0	EZ30	180-184 kW (245-250 PS)	LEGACY OUTBACK TRIBECA	09/03 [NEW]	<p>01-11244-01 10105-AA790</p>	<p>02-11244-01</p>				<p>61-11244-00 R 10944-AA010 90 Ø MLS</p>	<p>14-11605-01 11095-AA021 (8x)</p>	2x	<p>15-11479-01 L 13272-AA130 +13293-AA051 (3x)</p>	<p>12-10695-02 13207-AA110 (12x) +13211-AA100 (12x)</p>	<p>71-11481-00 6x 14035-AA460</p>	<p>70-31414-10 </p>	<p>81-10456-00 </p> <p>806738200 38,5x50,5 A SL RD FPM</p>	<p>81-53333-00 </p> <p>80678-6040 86x103 A SL LD MVQ</p>
3,6	EZ36D	183-206 kW (249-280 PS)	LEGACY OUTBACK TRIBECA	09/07 [NEW]	<p>01-11363-01 10105-AB690</p>	<p>02-11363-01</p>				<p>61-11249-00 R 11044-AA720 93 Ø 0,7 mm MLS</p>	<p>14-11605-01 11095-AA021 (8x)</p>	2x	<p>15-21567-01 R 13270-AA210 +13293-AA051 (3x)</p>	<p>12-10695-02 13207-AA110 (12x) +13211-AA100 (12x)</p>	<p>71-11481-00 6x 14035-AA460</p>	<p>70-31414-10 </p>	<p>81-10456-00 </p> <p>806738200 38,5x50,5 A SL RD FPM</p>	<p>81-53333-00 </p> <p>80678-6040 86x103 A SL LD MVQ</p>
					<p>61-11250-00 L 10944-AA061 93 Ø 0,7 mm MLS</p>				<p>15-21568-01 L 13272-AA150 +13293-AA051 (3x)</p>		<p>70-10695-00 AS 13211-AA100</p>	12x	<p>70-11562-00 ES 13207-AA110</p>	12x				

Haftungsausschluss

(für Katalog)

Alle Angaben in unserem Katalog wurden von uns sorgfältig geprüft, sind jedoch unverbindlich. Ersatzansprüche wegen Katalogangaben werden von uns nicht anerkannt. Der Käufer ist selbst verpflichtet, zu prüfen, ob unsere Teile für seine Zwecke geeignet sind. In allen Zweifelsfällen sollte Rücksprache mit unserem technischen Kundendienst erfolgen **Tel. +49 731 7046 999**.

Technische Weiterentwicklungen oder Änderungen bleiben vorbehalten, soweit damit keine Nachteile für den Kunden verbunden sind.

Angaben, Namens- und Markenzeichen, Beschreibungen, Nummern von Fahrzeugnummern und Herstellerzeichen, Original-Ersatzteilnummern der Fahrzeug- und Motorenhersteller u. a. sind ausschließlich für interne Zwecke gedacht. Solche Kennzeichnungen dürfen Fahrzeugbesitzern gegenüber nicht verwendet werden.

Wir weisen ausdrücklich darauf hin, dass alle von uns gelieferten Teile von geschultem Fachpersonal einzubauen sind. Reinz haftet für Fehler in diesem Katalog nur, wenn diese für den Kunden nicht offenbar erkennbar sind sowie nur bei Vorsatz und grober Fahrlässigkeit von Reinz, eines Vertreters oder eines Erfüllungsgehilfen. Dieser Haftungsausschluss gilt nicht im Rahmen

des Anwendungsbereichs des Produkthaftungsgesetzes und nicht bei Verletzung von Körper, Leben und Gesundheit, sowie bei der Verletzung von sog. Kardinalpflichten. Darüber hinaus ist unsere Haftung für Schäden, insbesondere für Personen-, Sach- oder Vermögensschäden, die unmittelbar oder mittelbar im Zusammenhang mit der Nutzung dieses Kataloges auftreten, sowie für nicht voraussehbare Schäden ausgeschlossen.

Reinz ist Inhaber aller Schutzrechte an den in diesem Katalog gespeicherten Daten. Kopie, Nachdruck, ganze oder teilweise Übernahme der Inhalte und Vervielfältigung, auch auszugsweise, ist nur mit unserer vorheriger schriftlicher Zustimmung sowie mit unserem Urheberrechtsvermerk zulässig.

Für Bestellungen, welche ab dem Erscheinungsdatum eines neuen Katalogs getätigt werden, sind alleine die Angaben des neuen Katalogs maßgeblich. Auf Angaben im Vorkatalog kann bei Neubestellungen nicht mehr zurückgegriffen werden.

Sofern Sie noch Fragen haben, bitten wir Sie, sich mit uns in Verbindung zu setzen.

VictorReinz.com/AGB

Exclusion of Liability

(for catalog)

All details in our catalog have been thoroughly checked by us but are however not binding. Right to damages on account of catalog details will not be recognized. The purchaser is obliged to check if our parts are suitable for their use. In all doubtful cases, the purchaser should consult our technical customer service under **+49 731 7046 999**.

We reserve the right to further technical developments or changes as long as no disadvantage for the customer results.

Details, name and trademarks, descriptions, numbers from vehicle numbers and manufacturer symbols, original vehicle replacement part numbers and engine manufacturer etc. are solely for internal use. Such labels must not be used with vehicle owners.

We specifically point out that all parts supplied by us must be assembled by trained specialists.

Reinz is liable for mistakes in this catalog only when they are not clearly recognizable for the customer, as well as by intent or gross negligence on the part of Reinz, its representative or vicarious agent. This exclusion of liability does not apply within the framework of the field of

application of the product liability laws and not by bodily harm, life and health, as well as by violation of cardinal duties. In addition, our liability for damages, especially personal, property or financial damages that occur directly or indirectly as a result of the use of this catalog, as well as non-foreseeable damages are excluded.

Reinz is the owner of all patent rights on the data stored in this catalog. Copies, reprints, whole or partial takeover of the contents and duplication even in excerpts are only permissible with our prior written approval, as well as with our copyright note.

For orders placed after the publication date of a new catalog, only the details in the new catalog are binding and no fall back to details in the previous catalog is possible.

In case you have further questions, do not hesitate to contact us.

VictorReinz.com/AGB

VictorReinz.com

reinz.info@dana.com

Technical Hotline +49 (0)731 7046-9 99

REINZ-Dichtungs-GmbH

Reinzstrasse 3-7
89233 Neu-Ulm
Germany
+49 (0)731 7046-0

VICTOR REINZ[®]

